

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-20546
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-7723
7. Lease Name or Unit Agreement Name: State AF
8. Well No. 1
9. Pool name or Wildcat Vacuum Abo Reef

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Penroc Oil Corporation	8. Well No. 1
3. Address of Operator P. O. Box 2769, Hobbs, NM 88241-2769	9. Pool name or Wildcat Vacuum Abo Reef
4. Well Location Unit Letter <u>M</u> : <u>510</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>West</u> line Section <u>8</u> Township <u>18S</u> Range <u>35E</u> NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:


PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Return to production. ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

RU JWS. Pull tbg & BHA. RU Signal wireline. Set CIBP @ 11,400'. Made 2 more runs and tagged & dump 35' cement on top of CIBP. RD wireline. TIH w/BHA & TAC. Set same, flange up wellhead. Ran 2-1/2x 1-1/2"x 24' pump & rods. Set PJ & return to pumping from the Abo.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE August 13, 2002  
Type or print name M. Y. Merchant Telephone No. 505-492-1236  
(This space for State use)

APPROVED BY [Signature] DATE AUG 19 2002  
Conditions of approval, if any: CARY W. WINK  
OGD FIELD REPRESENTATIVE / STAFF MANAGER