

NEW MEXICO OIL CONSERVATION COMMISSION

B-3936-1

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPERATE A WELL IN A FEDERAL LAND. USE "APPLICATION FOR PERMIT -" FORM 10-100 FOR SUCH PURPOSES.



GAS ☐
WELL ☐

OTHER:-

Name of Operator

TEXACO INC.

N.M. 'AA' State NCT-4

Address of Operator

P. O. Box 728 - Hobbs, New Mexico 88240

2

4. Location of Well

UNIT LETTER A , 660 FEET FROM THE East LINE AND 660

Vacuum Abo Reef

THE North LINE, SECTION 10 TOWNSHIP 18-S RANGE 34-E

15. Elevation (Show whether DF, RT, GE, etc.)

4027: (DF)

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data:

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK

PLUG AND ABANDON

FEMTOCAL NCP

TEMPORARILY ABANDON

CHANGE PLANS

CASSING TESTING CHART

PULL OR ALTER CASING

OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, work) SEE RULE 1103.

1. Set CIBP at 5200' and spot 35' (1 sx) cement on top.
2. Load hole with mud (25 sx gel per 100 bbls water).
3. Run freepoint, cut 2-3/8" casing and pull.
4. Spot 100' (35 sx) cement plug across casing stub, 50' above and 50' below.
5. If casing is cut and pulled below 3350', spot 100' (35 sx) cement plug across intermediate casing shoe.
6. Spot 20' (3 sx) cement plug at surface.
7. Clean location and install marker.

100' plug in $8\frac{5}{8}"$ at top 52ft.

18. I hereby certify that the information above is true and complete.

10450

Assistant District Superintendent

8-18-75

Only started by

APPROVED BY

APPROVED BY _____ Geologist

CONDITIONS OF APPROVAL, IF ANY: