

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

50. Indicate Type of Lease	State ☒ Fee ☐
51. State Oil & Gas Lease No.	06-2414

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL C-101 FOR SUCH PROPOSALS.)	
OIL WELL ☐ GAS WELL ☐ OTHER- Water Injection Well	7. Unit Agreement Name N. EK Queen Unit
1. Name of Operator Murphy H. Baxter	8. Farm or Lease Name Tract 7
2. Address of Operator P. O. Box 2040 Midland, Texas 79702	9. Well No. 3
3. Location of Well UNIT LETTER D 480 FEET FROM THE North LINE AND 853 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 18S RANGE 34E N.M.P.M.	10. Field and Pool, or Wildcat EK Yates 7 Rivers Queen
11. Elevation (Show whether DF, RT, GR, etc.) 4103' GL	12. County Lea

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☒ CHANGE PLANS ☐ OTHER ☐	REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

*Commission will be notified 24 hrs. prior to commencing work.

1. Trip in hole with CIBP. Set CIBP @ 4180'.
2. Spot 35' of cement on top of CIBP.
3. Displace hole with mud-laden fluid. Close pipe rams. Test plug and casing to 500#'s.
4. Perforate 4 holes @ 1700'. (Top of anhydrite @ 1740'). Circulate or squeeze 50 sks. or sufficient cement to isolate anhydrite section. WOC.
5. Tag and test plug to 500#'s.
6. Spot 50 sks. of cement above and below surface casing shoe @ 384'. WOC.
7. Tag plug. Cut bradenhead and weld steel plate on casing. Set P & A marker.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Chuck Sledge **Chuck Sledge** TITLE Petroleum Engineer DATE 8-13-87

ORIGINAL SIGNED BY **JERRY SIXTON**
 APPROVED BY DISTRICT 1 SUPERVISOR TITLE _____ DATE AUG 25 1987
 CONDITIONS OF APPROVAL, IF ANY:

THE UNIVERSITY OF CHICAGO
CHICAGO, ILLINOIS 60637