

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM C-101 FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name
2. Name of Operator: <u>Conoco Inc</u>		8. Farm or Lease Name: <u>Goodwin "30"</u>
3. Address of Operator: <u>P.O. Box 460 - Hobbs, NM 88240</u>		9. Well No.: <u>2</u>
4. Location of Well: UNIT LETTER <u>F</u> <u>1980'</u> FEET FROM THE <u>north</u> LINE AND <u>1980</u> FEET FROM THE <u>west</u> LINE, SECTION <u>30</u> TOWNSHIP <u>18S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat: <u>Arkansas Junction SA</u>
11. Elevation (Show whether DF, RT, GR, etc.):		12. County: <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOBS ☐
PLUG AND ABANDON ☐	OTHER ☐
CHANGE PLANS ☐	ALTERING CASING ☐
OTHER ☐	PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. Attempt to fish rods due to paraffin. C-1 H w/5 1/2" csq scraper to 5685'. Circ hole w/130 bbls 9.5 ppq mud (25 sxs salt gel/100 bbl 9 ppq brine) Spot 10 sxs class "C" neat cement from 5685'-5585' to isolate Clearyok. Set CIBP at 4574'. Spot 10 sxs class "C" neat cement from 4574'-4474'. Spot 50 sxs class "C" neat from 3246'-2746' to isolate 8 7/8" csq shoe & Yates. Spot 25 sxs class "C" neat cement from 1626'-1376' to isolate top of the anhydrite. Perf 2 squeeze holes thru 5 1/2" csq & 8 7/8" csq to 405'. Pump 9.5 ppq mud down 5 1/2" csq & establish circulation. Impd 230 sxs class "C" neat down 5 1/2" csq and circulate cement. Left cement in 5 1/2" csq at surface. Install P&H marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>DE FINNEY</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>6/16/87</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JUL 14 1987</u>
CONDITIONS OF APPROVAL, IF ANY:		