

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
CONOCO INC.
3. Address of Operator
P. O. Box 460, Hobbs, N.M. 88240
4. Location of Well
UNIT LETTER **F** **1980** FEET FROM THE **North** LINE AND **1980** FEET FROM
THE **West** LINE, SECTION **30** TOWNSHIP **18 S** RANGE **37 E** N.M.P.M.

7. Unit Agreement Name
8. Farm or Lease Name
GOODWIN
9. Well No.
2
10. Field and Pool, or Wildcat
Aok. Junction San Andres
12. County
LEA

15. Elevation (Show whether DF, RT, GR, etc.)
3750 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POOH w/ tbg. CO to 6900' w/ 5 1/2" CSG scraper. Perf w/ 2 JSPP 6751', 6756', 66', 70', 80', 89', 94'
2805', 17', 37', 4845'. Swbd tbg volume. Well dry. Acidize w/ 1500 gals. 15% HCl-NE-FE. Swbd well dry.
WtH w/ 5 1/2" CIBP @ 6300'. Spot acid from 4120'-6026. Perf 6026'-30', 6040'-50', 6070'-75', 6096'-99',
6112'-16', 6118'-6120', w/ 2 JSPP. Pckr @ 6000'. Acidize w/ 1000 gals. 15% HCl-NEFE. Swb 230 bbls fluid,
all water. Set CIBP @ 5954'. Dump cut on top of CIBP. Perf Bone Springs w/ 2 JSPP @ 5754', 58',
65', 5878', 84', 88'. Swbd 160 bbls fluid, all water. Set CIBP @ 5700'. Spot acid @ 4660'-4680'. Dump
cut on CIBP, Perf 4664', 71', 74', 4676' w/ 2 JSPP. San Andres Zone. Pckr @ 4617'. Swb 306 bbls fluid, w/
trace of oil. Acidize w/ 1000 gals. 15% HCl-NEFE. Swb 306 bbls. fluid, 10% oil. Reset PKR @ 4526'. Acid frac
San Andres perfs 4664'-4674' w/ 120 bbls. 15% HCl-NE-FE in 2 stages. Swb 75 bbls acid wtr, no oil. Continued
swabbing. POOH w/ 2 7/8" workstring. WtH w/ 150 jts 2 7/8" tbg. Run rods & pump. Place well on test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Wm A. Butterfield* TITLE Administrative Supervisor DATE 9/18/80
APPROVED BY *[Signature]* TITLE DATE
CONDITIONS OF APPROVAL, IF ANY:
None