

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-20663

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
E-6581

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Mack Energy Corporation

3. Address of Operator  
P. O. Box 960, Artesia, NM 88211-1354 (505) 748-1288

4. Well Location  
Unit Letter N : 660 Feet From The South Line and 1650 Feet From The West Lit

Section 30 Township 18-S Range 37-E NMPM Lea, NM County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set 5½ CIBP @ 6930' Cap W/35' cement
- 2) Load hole W/mud
- 3) Cut 5½ casing @ 4292' Pull out of hole
- 4) Spot 40 sacks cement, plug @ 5½ stub 4352' W.O.C., Tag cement top @ 4190'
- 5) Spot 30 sacks cement, plug @ 8-5/8 shoe 3248' W.O.C. No tag, respot cement plug W/60 sacks cement @ 3238' W.O.C., Tag cement top @ 3066'
- 6) Cut 8-5/8 casing @ 823', pull out of hole
- 7) Spot 35 sacks cement, plug @ 1760'
- 8) Spot 45 sacks cement, plug @ 8-5/8 stub 877' W.O.C., Tag cement top @ 804'
- 9) Spot 80 sacks cement, plug @ 13-3/8 shoe 417' W.O.C., Tag cement top @ 368' Respot, plug W/ 40 sacks cement W.O.C., Tag cement top @ 290'
- 10) SPot 15 sacks cement @ surface, set PA marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Elicia K. Kline TITLE District Secretary DATE 12/30/96

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY Johnny Robinson TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: