

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

| | |
|---|------------------------------|
| 5a. Indicate Type of Lease | |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |
| B-1113 | |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Marathon Oil Company | 8. Farm or Lease Name Warn State A/C 2 |
| 3. Address of Operator P. O. Box 2409, Hobbs, New Mexico 88240 | 9. Well No. 12 |
| 4. Location of Well UNIT LETTER <u>D</u> <u>560</u> FEET FROM THE <u>West</u> LINE AND <u>330</u> FEET FROM THE <u>North</u> LINE, SECTION <u>6</u> TOWNSHIP <u>18S</u> RANGE <u>35E</u> NMPM. | 10. Field and Pool, or Wildcat Vacuum-Glorieta |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3984' GR, 3996' KB | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Jarred on overshot for two days without success. Rigged up Rotary Wireline and backed off bumper sub right at the top of the overshot. Went in the hole with a packed off overshot and latched onto fish. Rigged up and pumped 150 barrels of a Polymer loss circulation pill down the tubing in an attempt to seal off the formation. Left the well shut in for two days. Pulled out of the hole with the packed off overshot. Went in the hole with a 3 7/8" burn shoe, one joint of wash pipe and 10 drill collars on 2 3/8" tubing. Milled out fish (overshot) and pipe dropped. Pulled out of the hole with burn shoe. Went in the hole with a 3 7/8" bit to 5544' (top of tubing anchor) without hitting any tight spots. Pulled out of the hole with the bit. Went in the hole with an impression block. Pulled out of the hole with the impression block. Block indicated junk on the top of the cut off joint above the tubing anchor. Went in the hole with a 3 5/8" overshot and attempted to catch cut off joint, without success. Pulled out of hole. Will go in the hole with a magnet in an attempt to clean off above the top of the cut off joint of tubing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Steven A. Pohler TITLE Production Engineer DATE November 2, 1984

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE NOV - 5 1984

CONDITIONS OF APPROVAL, IF ANY: