STATE OF NEW MEXICO			
INERGY AND MINERALS DEPARTME	OIL CONSERVA		Form C-103
DISTRIBUTION	P. O. BOX		Revised 10-1-78
SANTA PE	SANTA FE, NEW	MEXICO 87501	
FILE	-		5a. Indicate Type of Leuse
U.S.G.S.	-		State X Fee
LAND OFFICE	4		5. State Oli 6 Gas Lease No.
OPERATOR	J		B-1113
LOO NOT USE THIS FORM FOR FA	AND NOTICES AND REPORTS ON DEPOSALS TO PAIL ON TO DEEPLIN OF PLUG BA ION FOR PERMIT - " (FORM C-101) FOR SUC	WELLS ICA DIFFERENT RESERVOIR.	7. Unit Agreement Name
OIL X CAS WELL	0THER-		
2. Name of Operator			8, Farm of Lease Name
Marathon Oil Company			Warn State A/C 2
3. Address of Operator			9. Well No.
P. O. Box 2409	Hobbs, New Mexico 88240		12
4. Location of Well			10. Field and Pool, or Wildcat
	560 West	330	Vacuum-Glorieta
	<u>560</u> FEET FROM THE <u>West</u>		\mathcal{L}
THE NOT LINE, SECTI	ON TOWNSHIP 105	RANGE 5.5.5.	
Station (Show whether DF, RT, GR, etc.)			12. County
	<u>3984 GR, 399</u>	6 КВ	Lea AIIIIIIII
TE. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFDAM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
	·	OTHER	L_
OTHER	L_		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

Due to a Dynamometer run on the well and no casing pressure on the backside, it was believed that the casing may have salted off. On October 18, 1984 a pulling unit was moved on the well and the rods and pump pulled out of the hole. The blowout preventer equipment was installed, but could not release the tubing anchor. Rigged up NL McCullough, ran a free-point and found tubing 100% free above the anchor. Tubing anchor at 5544' - 5547'. Made chemical cut at 5562' below the anchor. Attempted to release anchor without success. Attempted to release anchor with a string shot with no results. Made another chemical cut at 5527'. Pipe was free, rigged down McCullough. Pulled out of the hole with the 2 3/8" tubing. Went in the hole with a joint of wash pipe and a 3 15/16" shoe. Went in the hole to 1754' and stuck the wash pipe. Worked pipe free. Pulled out of the hole with the wash pipe. Went in the hole with a 3 7/8" bit to 1920'. Pulled out of the hole. Went in the hole with a joint of wash pipe and a 3 15/16" shoe. Hit obstruction at 1754' and washed to 1868". Pipe became free and continued to top of fish. Washed over fish from 5527' to 5558'. Pulled out of hole with wash pipe. Went in the hole with a 3 15/16" overshot, jars, 6 - 3 1/8" drill collars on 2 3/8" tubing. Pipe became stuck at 1852'. Jarred on pipe and beat down without success. Rigged up Halliburton and pumped 500 gallons of 15% gelled acid down backside in an attempt to free pipe. Continued jarring and beating down on pipe without success of freeing

(cont.)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Steven A. Pohler/ Steven a. Retly mer_ Production Engineer	DATE		
Eddie W. Seay Arrente av <u>Oil & Gas Inspector</u>	OCT 3 0 1984		
CONDITIONS OF APPROVAL, IF ANY:			

Warn State A/C 2 Well No. 12 NMOCD - C103 Page 2

pipe. Rigged up NL McCullough and backed off pipe between the jars and bumper sub. Pulled out of the hole with tubing, drill collars and jars. Went in the hole with 3 13/16" conventional shoe on 1 joint of wash pipe, washed over top of overshot neck at ±1853. Will attempt to catch overshot neck and jar overshot free.

SAP/1p 10/25/84