

11/18/88

Memo

From

EDDIE W. SEAY
*Field Representative
Supervisor*

To Liz Roybal

Re your request for a change of operator from
Woodbine Pet. Co. to Damson Oil for the
Plains Unit Fed #6.

The BLM said that Woodbine did not do the proposed
recompletion work and the well was plugged by Damson.
They said they would not get a change of operator.
since they considered the intention filed by Woodbine
as cancelled.

Oil Conservation Division
PO Box 1980, Hobbs, New Mexico 88240

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

3. LEASE DESIGNATION AND SERIAL NO.

NM-0175774

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. UNIT ASSIGNMENT NAME

Plains Operating Area

2. FARM OR LEASE NAME

Plains Unit Fed

3. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Lusk Strawn

11. SEC., T., R., W., OR BLK. AND
STATE OR AREA

Sec. 21, T19S, R32E

12. COUNTY OR PARISH

Lea

13. STATE

NM

OIL WELL ☒ CAR WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Damson Oil Corporation

3. ADDRESS OF OPERATOR

3300 N. A, Bldg. 8, Suite 100, Midland, Texas 79705

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)

At surface

1980' FNL & 660' FWL

Unit E, SW/4 NW/4

5. DEPTH (Show whether DF, BT, CA, etc.)

3,602' KB

Box To Indicate Nature of Notice, Report, or Other Data

RE CASING
DATE

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Fully state all pertinent details, and give pertinent data, including estimated date of starting any give subsurface locations and measured and true vertical depths for all markers and zones perti-

/88 as follows:

at squeeze hole.

1,097'.

-BP.

- 4) Pulled up hole laying down 2-3/8" tbg to 6,500'. Mixed & ppd 50sx cmt plug. WOC 4 hrs. RIH w/tbg & tagged cmt @ 6,960'. POH w/tbg. Andy Cortez (BLM Agent) on location to witness plugging.
- 5) LD 5-1/2" csg. RIH w/2-3/8" tbg to 4,411'.
- 6) Circ'd hole & could not break circ. Mixed & ppd 30sx cmt w/2% CaCl. Pulled up hole w/tbg. WOC 4 hrs. Tagged TOC @ 4,291'. Could not circ hole. Mixed & ppd 40sx cmt plug.
- 7) Did not tag plug & did not break circ. Mixed & ppd 50sx cmt plug. WOC 6 hrs. Tagged cmt @ 2,667'.
- 8) Mixed & ppd 25sx cmt plug. Pulled up hole to 850'. Mixed & ppd 45sx cmt plug. Pulled up hole to 62'. Mixed & ppd 15sx cmt to surf.
- 9) Cut off wellhead. Installed P&A marker. Well plugged and abandoned.

I hereby certify that the foregoing is true and correct

SIGNED

D. R. Craig

TITLE District Engineer

DATE 10/11/88

(This space for Federal or State office use)

APPROVED BY

ORIG. SEC. 10.0001

TITLE

DATE

10-18-88

CONDITIONS OF APPROVAL, IF ANY:

Approved by BLM Agent on 10/11/88.
 Liability under BLM Act of 1906 until
 signed by BLM Agent on 10/11/88.

*See Instructions on Reverse Side

Need Change
 of Operator
 on this well
 From Woodbine
 Petroleum Co
 to Damson Oil