

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

(Include instructions on reverse side)

3. LEASE DESIGNATION AND SERIAL NO.

NM-0175774

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different level. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME Plains Operating Area	
2. NAME OF OPERATOR Damson Oil Corporation		8. FARM OR LEASE NAME Plains Unit 2nd	
3. ADDRESS OF OPERATOR 3300 N. A, Bldg. 8, Suite 100, Midland, Texas 79705		9. WELL NO. 6	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 660' FWL Unit E, SW/4 NW/4		10. FIELD AND POOL, OR WILDCAT Lusk Strawn	
11. SEC., T., R., M., OR B.L. AND QUARTER OR ALIA Sec. 21, T19S, R32E		12. COUNTY OR PARISH Lea	
13. ELEVATIONS (Show whether DF, RT, GR, etc.) 3,602' KB		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plug and Abandon 10/4/88 - 10/10/88 as follows:

- 1) MIRU PU. RIH to 7,000' & shot squeeze hole.
- 2) RIH w/CIBP & tbg. Set BP @ 11,097'.
- 3) Spotted 10sx cmt on top of CIBP.
- 4) Pulled up hole laying down 2-3/8" tbg to 6,500'. Mixed & ppd 50sx cmt plug. WOC 4 hrs. RIH w/tbg & tagged cmt @ 6,960'. POH w/tbg. Andy Cortez (BLM Agent) on location to witness plugging.
- 5) LD 5-1/2" csg. RIH w/2-3/8" tbg to 4,411'.
- 6) Circ'd hole & could not break circ. Mixed & ppd 30sx cmt w/2% CaCl. Pulled up hole w/tbg. WOC 4 hrs. Tagged TOC @ 4,291'. Could not circ hole. Mixed & ppd 40sx cmt plug.
- 7) Did not tag plug & did not break circ. Mixed & ppd 50sx cmt plug. WOC 6 hrs. Tagged cmt @ 2,667'.
- 8) Mixed & ppd 25sx cmt plug. Pulled up hole to 850'. Mixed & ppd 45sx cmt plug. Pulled up hole to 62'. Mixed & ppd 15sx cmt to surf.
- 9) Cut off wellhead. Installed P&A marker. Well plugged and abandoned.

8. I hereby certify that the foregoing is true and correct

 SIGNED D. R. Craig

 TITLE District Engineer

 DATE 10/11/88

(This space for Federal or State office use)

 APPROVED BY CHIEF, MINERAL RESOURCES

TITLE

 DATE 10-18-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

OCT 20 1988

OCD
HOBBS OFFICE