Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

CONDITIONS OF APPROVAL, IP ANY:

| DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 | WELL API NO. |
|---|---|
| DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 | 5. Indicate Type of Lease STATE X FEE |
| DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410 | 6. State Oil & Gas Lease No. LG-605 |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | 7. Lease Name or Unit Agreement Name |
| 1. Type of Well: OR. GAS WELL Y WELL OTHER | Superior "C" State |
| 2. Name of Operator | 8. Well No. |
| Harvey E. Yates Company | #1 |
| P.O. Box 1933, Roswell, New Mexico 88202 | 9. Pool name or Wildcat Und. Bone Springs |
| 4. Well Location Unit Letter K: 1980 Feet From The South Line and 1980 Feet From The West Line | |
| Section 16 Township 19S Range 32E | NMPM Lea, N.M. County |
| Section 10 Idward 193 Range 32L [] 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | NMPM Lea, N.M. County |
| ////////////////////////////////////// | |
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING | |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT | |
| PULL OR ALTER CASING CASING TEST AND CEMENT JOB | |
| OTHER: PB & te | st Bone Spring |
| 12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed work) SEE RULE 1103. | |
| 12/8/89 POOH w/broken pkr, Set CIBP @ 12,530' + 35' cmt on top, New PBTD @ 12,495' (ok per Paul K. 12/6/89). | |
| 12/9/89 Perf 4 sqz perfs @ 10,480' & set ret @ 10,380' | |
| 12/10/89 Cmt from 10,480' est 5500' w/100' cap on Wolfcamp from | |
| 10,380-10,480'; New PBTD @ 10,380', (Cmt w/1300 sks cmt.) 12/14/89 Ran CBL (TOC @ 6830'), Perf 9316'-9407' (oa) 10 holes; Acdz w/2500 gals 7 1/2% SRA | |
| 12/29/89 Frac perfs 9316-9407' w/100,000 gals WF-45 & 100,000# 16/20 Carbolite | |
| 1/4/90 Put on jet pmp to pmp back frac load & test zone 9316-9407', SN & pkr @ 9131' (186' above perfs) | |
| | |
| | |
| I hereby certify that the information above to true and complete to the first of my knowledge and belief. Prod Mgr/Eng | 1/5/90 |
| TYTEOR PRINT NAME Ray F. Nokes | TELEPHONE NO. 623-6601 |
| , | |
| (This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON | JAN 1 1 1990 |
| ORIGINAL SIGNED ET STATES | DATE |