

N.M.O.G.D. COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

MAY 27 1981

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR U.S. GEOLOGICAL SURVEY
Tenneco Oil Company HOBBS, NEW MEXICO
3. ADDRESS OF OPERATOR
6800 Park Ten Blvd., San Antonio, TX 78213
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL and 660' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☒
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE NM-0319697
NM-0349697
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Hudson Federal
9. WELL NO.
#1
10. FIELD OR WILDCAT NAME
Lusk Strawn
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 5, T19S, R32E
12. COUNTY OR PARISH Lea 13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3673'

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. RUSU. Swab test and evaluate. Take fluid sample.
2. Unseat Brown packer set at 11253 and tag T.D. Pull tubing and packer and tally out of hole. Clean out fill if necessary.
3. Perforate 11364-76 with 1 JSPF.
4. Run tubing and treating packer to be set \pm 11250' and swab test. Evaluate for acid treatment. If necessary, acidize per recommendation.
5. If treatment is not necessary, run tubing and rods.
6. Space and hang on.
7. NDBOP. RDSU.
8. Put well on production.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED

May Hall

TITLE Production Analyst DATE 5/22/81

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

MAY 28 1981

JAMES A. GILLHAM
DISTRICT SUPERVISOR

RECEIVED

JUN 2 1981

OIL CONSERVATION DIV.