

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002520961
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-9721
7. Lease Name or Unit Agreement Name Texaco Cities Service State Com
8. Well No. 1
9. Pool name or Wildcat Lusk Morrow

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Texaco Inc.	
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>East</u> Line and <u>1980</u> Feet From The <u>North</u> Line Section <u>32</u> Township <u>19S</u> Range <u>32E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3533' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

05/16/89 thru 07/31/89

- 1) MIRU PU. Bled well down. Killed w/65 bbls wtr.
- 2) Ran 2-5/8" mill to 12,852' and cir hole cln.
- 3) Tested csg to 2500 psi. Held O.K.
- 4) Perforated 2-7/8" csg w/2 JSPF @ 12,318-319,422,551,566,558,588-589'.
- 5) Acidized w/3000 gals 15% NEFE.
- 6) RDPU.
- 7) Schlumberger set CIBP @ 12,520' and dumped 35' cmt on top. PBDT 12,485'. Well shut-in. Workover unsuccessful.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. A. Head TITLE Area Manager DATE 09/26/89
TYPE OR PRINT NAME J. A. Head TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY Paul Flauts TITLE Geologist DATE SEP 20 1989

CONDITIONS OF APPROVAL, IF ANY:

7/10/89, 10/1/89