

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 11087

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

El Paso Products Company

3. ADDRESS OF OPERATOR

c/o Hobbs Pipe & Supply Co., Box 2010, Hobbs, N. M.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1650' FSL & 990 FWL

7. UNIT AGREEMENT NAME

Lusk Deep Unit

8. FARM OR LEASE NAME

Lusk Deep

9. WELL NO.

11

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

17 - 19S - 32E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

UK

12. COUNTY OR PARISH

Lea

13. STATE

N. M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Proposed Plugging Procedures:

1. Spot a 25 sx cement plug to cover existing perforations.
2. Spot a 25 sx cement plug at stub of 4-1/2" casing.
3. Spot a 35 sx cement plug at base of 8-5/8" casing (3724').
4. Spot a 25 sx cement plug at 2500' - 2600', or in and out of 8-5/8 stub.
5. Spot a 25 sx cement plug at 700' - 800'.
6. Spot a 10 sx cement plug at top.
7. Hole will be loaded with mud-laden fluids and a 4" regular marker erected.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE

9/16/71

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

J. L. GORDON
GENERAL DISTRICT ENGINEER

RECEIVED

SEP 21 1971

**OIL CONSERVATION COMM.
HOBBS, N. M.**