

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-21054
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1306-1
7. Lease Name or Unit Agreement Name: Vacuum Glorieta West Unit
8. Well No. 128
9. Pool name or Wildcat Vacuum Glorieta

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	2. Name of Operator Texaco Exploration & Production, Inc.
3. Address of Operator P. O. Box 3109, Midland, TX 79702	4. Well Location Unit Letter <u>G</u> : <u>1650</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>6</u> Township <u>18S</u> Range <u>35E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3983-DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- Set 2 7/8" CIBP @ 4900', fill 2 7/8" csg w/50 sxs cmt 4900'-3000' (Seismic Perfs)
- Perf 6 holes @ 2850', squeeze 50 sxs cmt 2850'-2600' (B-Salt-Yates) WOC Tag
- Perf 6 holes @ 1650', squeeze 50 sxs cmt 1650'-1400', (T-Salt-11 3/4" Sho) WOC Tag
- Fill 2 7/8" csg w/40 sxs cmt 1400'-Surf
- Install dry hole marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James T. Corbitt TITLE FACILITY ENGINEER DATE 10/6/00
Type or print name JAMES T. CORBITT Telephone No. 915 688-4436
(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any:



PLUGGING & ABANDONMENT WORKSHEET

(2 STRING CSNG)

OPERATOR TEXACO EXPLORATION & PRODUCTION
LEASENAME VACUUM COLORIETA WEST UNIT

SECT 6 TWN 18-S RNG 35 E
FROM 1650 (NSL) 1980 (EWL)
TD: FORMATION @ TD Glorieta
PBDT: FORMATION @ PBDT

Circ CMT
2 7/8 x 11 3/4
600 SXS
9/12/80

11 3/4
@ 1500
TOC SURF
PERF 6 HOLES
@ 1650'

PERF 6 HOLES
@ 2850

Glorieta

2 7/8
@ 6320
TOC 3474

TD 6320

	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE	11 3/4	1500	SURF	Circ	
INTMED 1	2 7/8	6320	3474	Bond Log	
INTMED 2					
PROD					
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					
	CUT & PULL @			TOP - BOTTOM	
INTMED 1			PERFS	-	
INTMED 2			OPENHOLE	-	
PROD					

*REQUIRED PLUGS DISTRICT I

RUSTLER (ANHYD)	
YATES	
QUEEN	
GRAYBURG	
SAN ANDRES	
CAPTAN REEF	
DELAWARE	
BELL CANYON	
CHERRY CANYON	
BRUNBY CANYON	
BONE SPRING	
COLORIETA	
BLINEBRY	
TUBB	
DRINKARD	
ABO	
WC	
PENN	
STRAWN	
ATOKA	
MORROW	
MISS	
DEVONIAN	

PLUG	TYPE	SACKS	DEPTH
PLUG	PLUG	CMNT	
EXAMPLES			
PLUG #1	OH	35 SXS	6400'
PLUG #2	SHOE	50 SXS	5350'-5450'
PLUG #3	CIBP/35'		4800'
PLUG #3	CIBP	25 SXS	4800'
PLUG #4	STUB	50 SXS	3600'-3700'
PLUG #5	RETNR SQZ	200 SXS	400'
PLUG #6	SURF	10 SXS	0-10'
PLUG #1	CIBP	4900'	SEISMIC
PLUG #2		50 SX	4900-3000
PLUG #3	B-SALT	50 SX	2850-2600
PLUG #4	SHOE	50 SX	1650-1400
PLUG #5	SURF	40 SX	1400-SURF
PLUG #6			
PLUG #7			
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #			
PLUG #			

PERFS

T-SALT

