

Submit 3 copies
to Appropriate
District Office

Energy, Minerals and Natural Resources Department

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-21292
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-1113
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	127
9. Pool Name or Wildcat	VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3976' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	BHL: G, 6, 18S, 35E, 1576' N, 2885' W
Unit Letter	F
1650 Feet From The	NORTH Line and 1650 Feet From The WEST Line
Section	6
Township	18S
Range	35E
NMPM	LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3976' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	SPUD HORIZONTAL ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-08-00: MIRU. TAKE OFF COLLAR, INSTL SCREW ON FLANGE. NUBOP. PU TBG W/BIT & TAG CIBP @ 5814'.
 9-09-00: TIH W/SANDLINE DRILL & TAG CIBP @ 5870'. UNABLE TO KNOCK CIBP OUT.
 9-10-00: HIT CIBP. TOH & RECVR RUBBER & METAL. PU BIT, DC'S & TIH ON 2 3/8" TBG. TAG CIBP. TIH W/CMT RET & SET @ 5888'.
 9-11-00: MIX & PUMP 150 SX CL H, FOLLOWED BY 100 SX CL H NEAT. SQZ PERFS W/42 BBLS CMT. REV 10 BBLS CMT TO TRUCK. TOH W/TBG.
 9-15-00: MIRU KEY RIG #118. TIH W/188 JTS DP & MILLS. TAG CIBP @ 5887'. TIH W/WHIPSTOCK TO 5875'. TIH W/SDI GYRO FOR SURVEY. SET WHIPSTOCK W/85 DEG ORIENTATION ON BTM.
 9-16-00: SET WHIP @ 85 DEG AZIMUTH. MILL FR 5878-79, 5881. DRILL FR 5885, 91, 5916, 6007-40, 6134, 65, 97, 6228, 48, 60, 67, 91, 94, 6353, 66, 6447, 57, 6500, 11, 60, 6638, 44, 6791, 96, 6916, 7134.
 9-20-00: TIH W/BOX TAP, BMPR SUB, JARS & DC'S. LATCH ONTO WHIP & JAR LOOSE. TIH W/RBP. SET @ 5783'. NDBOP. ND FLOWLINE. INSTL RENTAL BOP. RIG DOWN & RELEASE @ 2000 HRS ON 9/19/00.
 9-22-00: UNLOAD TBG & HYDRIL. TALLY ALL PIPE. TIH W/2 3/8" TBG. TIH TO 5700'. RBP @ 5783'.
 9-23-00: TOH & LD RBP. TIH W/SUBS & TBG. PKR SET @ 5775.67. TEST TO 1000 PSI-OK.
 9-28-00: STIMULATE GLORIETA: 40,000 GALS WF 130 @ 15 BPM. FLSH W/3000 GALS WF 130. FLOW BACK AFTER STIMULATION.
 9-29-00: MIRU WORKOVER RIG. KILL W/40 BBLS 10# BW. OPEN BYPASS. UNSET PKR. NDTREE. TIH W/KILL STRING TO 1900'.
 9-30-00: TIH W/2 3/8" TBG, CHECK VALVE, PUMP. NDBOP. INSTL FLOW TREE & CONNECT TO FLOWLINE. TEST PUMP-OK. RIG DOWN & REL.
 10-01/10-02-00: PUMPING AND TESTING
 10-03-00: ON 24 HR OPT. PUMPED 464 BO, 89 BW, 248 MCF.

TOP OF WINDOW: 5878, BOTTOM OF WINDOW: 5882'

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 11/17/00
 TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY:

TITLE

ORIGINAL SIGNED BY
PAUL F. KAUTZ
PETROLEUM ENGINEER

DATE

APR 05 2002

DeSoto Nichols 12-1-00

5
C
r