

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088WELL API NO.
3002521424

5. Indicate Type of Lease

STATE ☒FEE ☐

6. State Oil & Gas Lease No.

B-1306-1

7. Lease Name or Unit Agreement Name

New Mexico "R" State NCT-2

8. Well No.

5

9. Pool name or Wildcat

Vacuum Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒GAS
WELL ☐OTHER ☐

2. Name of Operator

Texaco E&P Inc.

3. Address of Operator

P.O. Box 730 Hobbs, NM 88240

4. Well Location

Unit Letter B : 330 Feet From The North Line and 1650 Feet From The East LineSection 2Township 18SRange 34E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4011 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data.

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐REMEDIAL WORK ☐ALTERING CASING ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☒PULL OR ALTER CASING ☐CASING TEST AND CEMENT JOB ☐OTHER: ☐OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. 3-9-95 Notify NMOCD of intent to plug & abandon well.
2. 3-10-95 Rig up wire line set CIBP @ 4790. Pick up 2-1/16" workstring, TIH w/tag CIBP; mix & circ. well w/25# per bbl. salt gel mud.
3. 3-10-95 Cap CIBP @ 4790 w/10sx cmt. cal TOC 4566'.
4. 3-13-95 Jet cut csg. 2700'. pipe not free.
5. 3-14-95 Spot 10sx cmt. @ 2750' displace to 2346' talk to NMOCD Paul Kaute.
6. 3-14-95 Jet cut csg. @ 1778. Spot 125sx cmt. plug @ 1778' WOC & tag 3-15-95 no cmt.
7. 3-15-95 Spot 125sx cmt. plug @ 1778' WOC 4 hr. Tag @ 1708'.
8. 3-15-95 Spot 125sx cmt. plug @ 1708' WOC & tag 3-16-95 @ 1320'.
9. 3-16-95 Spot 45sx cmt. plug @ 400'. Cal TOC 296'.
10. 3-16-95 Spot 15sx cmt. plug @ 30-surface.
11. 3-17-95 Dig out cellar; cut off well head; cap well & install dry hole marker
Rig down & move off.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. CalderTITLE P&A SupervisorDATE 3-17-95

TYPE OR PRINT NAME

TELEPHONE NO.

This space for State Use)

OIL & GAS INSPECTOR


MAY 16 1995

APPROVED BY Carmy W. Hill TITLE _____ DATE _____

CONDITIONS OF APPROVAL IF ANY:

P&A: 3-17-95

TEXACO E&P INC.
NM "R" State NCT-2 No. 5
API# 30 025 21424



330 FNL & 1650 FEL
SEC 30, TWN 18 S, RANGE 35 E
ELEVATION: 3985 ES
COMPLETION DATE: 03-01-77

COMPLETION INTERVAL: 5020 - 5946 (SA)

OFFICE