

## ATTACHMENT

OXY USA Inc. #4 Wyatt A-Federal  
Sec. 33-T17S-R33E  
Lea County, New Mexico

- Class C cement plug @ 4090 - 3946', across the top of the Queen Formation. Displaced plug w/mud laden fluid and POOH w/tubing.
3. RIH w/casing cutter and cut the 4-1/2" casing @ 3110' and tried to work the casing free with no success. RIH w/tubing and packer and set the packer @ 2804' and established an injection rate of 1-1/2 BPM @ 2000# but was unable to break circulation in the 4-1/2" x 8-5/8" annulus. Released the packer and POOH w/tubing and packer.
  4. RIH w/2-3/8" OE'd tubing to 3173' and spotted a 25 sack Class C cement plug @ 3173 - 2819', 1/2 in and 1/2 out of the 8-5/8" casing shoe @ 3105'. Displaced the plug w/mud laden fluid and POOH w/tubing.
  5. RIH w/casing cutter and cut the 4-1/2" casing @ 1994' and POOH w/4-1/2" casing. RIH w/2-3/8" OE'd tubing to 2044' and spotted a 17 sack Class C cement plug @ 2044 - 1944', 1/2 in and 1/2 out of the 4-1/2" casing stub @ 1994'. Displaced the plug w/mud laden fluid and POOH w/tubing and WOC for 48 hrs. RIH w/2-3/8" OE'd tubing and tagged the cement plug @ 1977'. POOH w/tubing to 1449'.
  6. Spotted a 40 sack Class C cement plug @ 1449 - 1305', across the top of the Salt Zone. Displaced the plug w/mud laden fluid and POOH w/tubing to 391'.
  7. Spotted a 40 sack Class C cement plug @ 391 - 247', 1/2 in and 1/2 out of the 13-3/8" casing shoe @ 310'. Displaced the plug w/mud laden fluid and POOH w/tubing to 60'.
  8. Spotted a 18 sack Class C cement surface plug @ 60' - surface. CO WH and installed a 4" dry hole marker to designate a plugged and abandoned location.

The plugging of this well was witnessed by Mr. R.B. Dillow with the BLM located at Carlsbad, New Mexico.

RECEIVED

JUL 10 1989

HOME OFFICE