

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-21619
5. Indicate Type of Lease
STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
B-1031

7. Lease Name or Unit Agreement Name:
Central Vacuum Unit

8. Well No. 116

9. Pool name or Wildcat
Vacuum Grayburg - SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Texaco Exploration & Production, Inc.

3. Address of Operator
P. O. Box 3109, Midland, Tx 79702

4. Well Location
Unit Letter P : 990 feet from the South line and 870 feet from the East line
Section 6 Township 18S Range 35E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RIH Tag CIBP @ 4593' (Grayburg-San Andres) spot 25 Sx plug 4593'-4000' Tag 3805'
2. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL
3. Spot 25 Sx plug 3800'-3600' (Queen) Tag @ 3515'
4. Perf 6 holes @ 2800' unable to sqz spot 25 sx plug 2847'-2600' (B-Salt, Yates) Tag @ 2517'
5. Perf 6 hole @ 1605', Sqz w/125 Sx plug 1605'-1200' (7 5/8" shoe-T-Salt) Tag @ 1125'
6. Circ cmt 60' to surface w/15 sx. Install dry hole marker. 9/20/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER DATE 9/20/01

Type or print name Jimmy BAGLEY Telephone No. (915) 683-4996
(This space for State use)

APPROVED BY Johnny Robinson TITLE _____ DATE _____
Conditions of approval, if any:

Σ GWW