

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate*
(Other Instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0117784

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Drilling</u>	7. UNIT AGREEMENT NAME <u>BUFFALO Federal UNIT</u>
2. NAME OF OPERATOR <u>PAN AMERICAN PETROLEUM CORPORATION</u>	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR <u>Box 68, Hobbs, N.M.</u>	9. WELL NO. <u>9</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>1650' FNL x 2310' FWL Sec. 34 (Unit 7, SE 1/4 NW 1/4)</u>	10. FIELD AND POOL, OR WILDCAT <u>CORBIN Queen South</u>
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>34-18-33 NMPM</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>3787' R.D.B</u>	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD-4570. On 12-15-66, 4 1/2" OD 9.5# J-55 Casing was set at 4570 w/ 300# Incon Cement. Tested casing w/ 2000 psi for 30 minutes. Test O.K. Perforated 4488-4503, 07-18, 22-26 w/ 25PF. Acidized w/ 2000 gal Reg. Fraced w/ 30,000 gal oil, 3000# sand, 3000# beads. Evaluated. No oil. Some gas. Squeezed Perfs 4488-4507 w/ 125sx. Evaluated perfs 4507-4526. Stimulated w/ 2000 gal acid; Fraced w/ 5000 gal oil, 5000# sand. Evaluated - Dry. Set CIBP@4400' and perforated 4248-4272 w/ 25PF. Acidized w/ 2000 gal 15%. Evaluated. Dry. Shut In - Propose to P+ A as follows: Spot 20 5x plug 4400-4072. Cut + pull 4 1/2" Casing from appx. 2560. Spot 25sx. in + out of 4 1/2" stub; 25sx. 1455-1345; 25sx in + out of 8 7/8" CSA 264; 10sx @ surface w/ P+ A marker. Make final cleanup + restore ground to contour. P+ A procedure. pu. tile conv. Monu. A known se zone on 4/1/67.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED DATE

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER0-4- USGS-N
1- NSW
1- SUSP
1- RRY
1- CONOCO
1- STATE LAND