

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E 1774-2	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator KOCH EXPLORATION COMPANY		8. Farm or Lease Name Rock Island State
3. Address of Operator P.O. Box 2256, Wichita, KS 67201		9. Well No. 1
4. Location of Well UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>17S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat Grayburg SA
15. Elevation (Show whether DF, RT, GR, etc.) 4092 KB		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIATION WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug & Abandonment Data: Plugging Contractor: Caffey Inc., Hobbs, NM
6/21/85

1. Ran & set 5-1/2" CIBP @ 4600' w/5 sx cmt. plug on top, 4600-4557'.
2. Circ. hole (csg.) w/mud.
3. Cut 5-1/2" csg. w/wire line csg. cutter @ 4140' & @ 3000' unable to pull.
4. Cut 5-1/2" csg. w/wire line csg. cutter @ 2810' pull & lay same down.
5. Spot 15 sx cmt. plug 4189-4058'.
6. Spot 15 sx cmt. plug 3055-2954'.
7. Spot 30 sx cmt. plug 2866-2728'.
8. Cut 8-5/8" csg. @ 1000' w/wire line cutter. Pull & lay same down.
9. Spot 50 sx cmt plug 1040-914'.
10. Spot 75 sx cmt. plug 378--276'.
11. Spot 10 sx cmt. plug to surface, installing regulation dry hole marker.
12. Plugging completed 6/21/85.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Vernon J. Lowe

TITLE Operations Mgr.

DATE 8/6/85

APPROVED BY Jackie Griffin

TITLE OIL & GAS INSPECTOR

DATE FEB 11 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG - 9 1980

HOME OFFICE