

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-1774-2
7. Unit Agreement Name
8. Farm or Lease Name Rock Island State
9. Well No. #1
10. Field and Pool, or Wildcat N. Vacuum <i>Gray, SA</i>
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Koch Exploration Company
3. Address of Operator P. O. Box 2256 Wichita, Kansas 67201
4. Location of Well UNIT LETTER <u>C</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>17S</u> RANGE <u>34E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4092' KB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Plug Back Completion, San Andres</u> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The below operations have been performed & completed on Rock Island State #1:

- 1) Perf San Andres formation, 4678-84' (12 holes), 4687-90' (6 holes), 4707' (2 holes), 4712' (2 holes), 4719' (2 holes), 4731' (2 holes), 4747' (2 holes), total of 28 holes.
- 2) Run RBP & packer on 2-3/8" tbg, set RBP @ 4780', test plug to 3000 psi, set packer @ 4670'.
- 3) Treat perfs w/23,000 gallons 15% HCL & retarded acid.
- 4) Swab load back.
- 5) Released packer & RBP & pulled same.
- 6) Run & set CIBP, dump 2 sx cmt on top of BP, CIBP set @ 10,700' KB.
- 7) Ran tbg & rods 11-21-83, hung well on for pumping & released pulling unit.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Vernon J. Lowe* TITLE Operations Manager DATE November 22, 1983
ORIGINAL SIGNED BY **EDDIE SEAY**
APPROVED BY **OIL & GAS INSPECTOR** TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

m