

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E - 1356	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name	
2. Name of Operator Pennzoil Company		8. Farm or Lease Name Rock Island "B" State	
3. Address of Operator P.O. Drawer 1828, Midland, Texas 79702		9. Well No. 1	
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>4</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Vacuum Lower Wolfcamp North	
15. Elevation (Show whether DF, RT, GR, etc.) 4079 GR		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Test additional pay in lower Wolfcamp zone.</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 3/16/81 MI & RU pulling unit. Pull rods and pump. Run tbg to btm and check for fill. Clean out if necessary.
- 3/17/81 RIH w/Baker model "R" pkr, spot acid and pull up to 10,875'. Set pkr and install tree.
- 3/18/81 Run tbg gun and perf at 10,922-27 and 10,932-35 w/2 JSPF. Swab test and treat if necessary.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. V. Dullin</u>	TITLE <u>Operations Engineer</u>	DATE <u>3/6/81</u>
Orig. Signed by Les Clements Oil & Gas Insp.		
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		