

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

06-1633

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator Conoco Inc	8. Farm or Lease Name East EK Unit
3. Address of Operator P.O. Box 460, Hobbs, nm 88240	9. Well No. 7
4. Location of Well UNIT LETTER A 2310 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 22 TOWNSHIP 18S RANGE 34E NMPM.	10. Field and Pool, or Wildcat East EK Queen 4#
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. MIPD, scrape casing to 4300', pull up to 4400' and set CIBP.
2. Spot 250x cement on top of CIBP, bring cement fill up to 4232', spot a 50' cement plug from 310'-3010' (75x±), spot 1 bbl of 10% acetic acid from 458'-396', 4 JSPE, perforate the 4-1/2" production casing at 458', if circulation can be broken, circulate 150x cement down casing through perfs @ 458', approximately 50x should reach surface, displace cement to 358' with mud, shut down and WOC 1/2-1 hr.
3. Tag TOC inside casing @ 358', If circulation cannot be established, spot a cement plug from 458'-358' (75x±), WOC 1/2-1 hr, tag top of cement inside casing @ 358', fill the intermediate annulus with cement to surface using 1" pipe as necessary. Spot cement from 100'-0' (75x±), cut casing 3 below restored ground level, fill the casing from the cement plug to the surface with cement, sand or gravel. Erect a permanent steel P+M marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ann Bull TITLE Administrative Supervisor DATE 8-11-86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

TITLE

DATE

AUG 14 1986

AMOCO-Hobbs