

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRICT	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATIONS	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-1113-1

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name Central Vacuum Unit
2. Name of Operator Texaco Producing Inc.	8. Farm or Lease Name
3. Address of Operator P.O. Box 728, Hobbs, NM 88240	9. Well No. 118
4. Location of well UNIT LETTER <u>N</u> <u>1650</u> FEET FROM THE <u>West</u> LINE AND <u>990</u> FEET FROM THE <u>South</u> LINE, SECTION <u>6</u> TOWNSHIP <u>18S</u> RANGE <u>35E</u> NMPM.	10. Field and Pool, or Wildcat Vacuum Grayburg San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3987' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) RU PU. TOH w/rods and pump. Install BOP.
- 2) TOH w/tbg.
- 3) TIH w/4 3/4" bit on 2 3/8" tbg and clean out to 4730': Circ. clean. Spot 600 gal ammonium bicarbonate across open hole.
- 4) TOH w/bit.
- 5) Perforate 5 1/2" csg at 4489, 94, 97, 4510, 14, 24, 55, 62, 67, 71, 77, 88, 91, 4617, 25, 40, 4754, 60, 63, 71, 74, 80, 4705 (2 spf).
- 6) Spot sand to 4690.
- 7) TIH w/pkr, set pkr at 4000'. Load annulus w/prod. water.
- 8) Acidize perms 4489-4686 w/9000 gal. gelled 15% NEFE with 40 ball sealers and 1500 lb. rocksalt. Air 4.5 BPM.
- 9) TOH w/pkr.
- 10) TIH w/hydrostatic bailer and clean out sand.
- 11) Run tbg, rods, and pump and return to production. Opt 46 BO, 16 BW.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. W. Browning TITLE District Admin. Supervisor DATE 03/21/86

ORIGINAL SIGNED BY JERRY TEXTON

APPROVED BY DISTRICT SUPERVISOR

TITLE

DATE APR 2 - 1986

CONDITIONS OF APPROVAL, IF ANY: