

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
Roswell, N.M. 01177-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☐ WELL GAS ☐ WELL OTHER ☒ **Dry**
2. NAME OF OPERATOR
TEXO OIL COMPANY
3. ADDRESS OF OPERATOR
728 First Wichita National Bldg., Wichita Falls, Texas
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below)
At surface **2310' FSL and 330' FWL of Sec. 35, T-188, R-33E**

7. UNIT AGREEMENT NAME

XXXXXXXXXX

8. FARM OR LEASE NAME

Buffalo Unit

9. WELL NO.

11

10. FIELD AND POOL, OR WILDCAT

South Corbin Queen

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 35, T-188, R-33E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3781 GR; 3793 DF, 3794 KB

12. COUNTY OR PARISH

Lea

13. STATE

New Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texo Oil Company Buffalo Unit Well No. 11, T.D. 4603', plugged with following approved procedure:

No. 1 plug 4300' - 4200', 35 sx. displaced thru drill pipe
No. 2 plug 3000 - 2900', 30 sx. " " " "
No. 3 plug 1530' - 1430', 30 sx. " " " "
No. 4 plug 300' - 200', 30 sx. " " " "
No. 5 plug 10' - 0, 5 sx. " " " "

No. 5 plug in top of surface casing w/4" diameter marker

18. I hereby certify that the foregoing is true and correct

SIGNED

Betty Crawford

TITLE

Agent

DATE

8/10/68

(This space for Federal or State office use)

APPROVED

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 13 1969

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.