Form 9-331		HAUTED CTATEC		1
(May 1963)	UNITED STATES SUBMIT IN TRIPLICATE* DEPARTME OF THE INTERIOR (Other instruction on re-			Budget Bureau No. 42-R142
	DEFAR	KIOK verse side)	5. LEASE DESIGNATION AND SERIAL NO.	
GEOLOGICAL SURVEY				LC-032233 (L)
(Do not	SUNDRY NC use this form for pro- Use "APPLI	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
1.	Use AFFLI	CATION FOR PERMIT : for suc	h proposals.)	
WELL X	GAS WELL OTHER	7. UNIT AGREEMENT NAME		
2. NAME OF OPE		8. FARM OR LEASE NAME		
3. ADDRESS OF O	le Oil & K	Bowers A Federal		
		9. WELL NO.		
Box 16	WELL (Report location	28		
See also space	e 17 below.)	10. FIELD AND POOL, OR WILDCAT		
At sullace		Hobbs Blinzbry		
660	ESI 990	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
660 FSL, 990 FWL				S-29, T185, R-38E
14. PERMIT NO.		15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
		Later		Lea N. Mex
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other				Other Data
NOTICE OF INTENTION TO:				JENT REPORT OF:
TEST WATER	SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TR	EAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR AC	IDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL		CHANGE PLANS	(Other) Perforation	& Completing
(Other) (NOTE: Report results of Completion or Recomple				of multiple completion on Well etion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, i proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.) *				
Drilled to T.O. @ 6000'. on 3-31-69. Rana set 5989'				
5/2"00 15.5# \$ 14# Osg @ 6000. Cemented Trinity Lite Cont wy/z# SR Gel Flake and +				uy 250 sax
Triniti	followed by			
200 sax incor neat cont. WOC 24 hrs. Test wy 1000ps/				
for 30 min wy no pressure drop. R.U. & perc. 51/2"				
CSQ WY 7 RASE JET Shorts a (1 for Fact)				
CSQ WY Z RASE Jet Shots per ft, from 5856-58;				
5860-62'; 5874-76', 5880-82', 5897-5900' and 5925-28'. Acidized by 500gal. NE acid @ 1000 PSI. Swabbed				
	α	. JWabbed		
Well.	Would.	t pump and		
Completed well as pumping oil well. Preparing				
to tak	ke poter			
	, , ,			

18. I hereby certify that the foregoing is true and correct

SIGNED A. F. Clemmer TITLE Unit 1/2ad DATE 4/17/69

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

APR'S. SE