NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.		Sa. Indicate Type of Lease
LAND OFFICE		State Fee X
OPERATOR		5. State Off & Gas Leave No.
		a maa mada mada mada mada mada mada mad
SUNDR DO NOT USE THIS FORM FOR FOR UCL TAPE. ICAT	Y NOTICES AND REPORTS ON WELLS BOOMS TO CALL ON TO DEFILE OF FUS BACK TO A DIFFERENT RESERVOIR.	
1.		7. Unit Agreement Name
OIL CAS WELL	OTHER-	
2. Nume of Operator		8. Form of Lease Name
Gulf Oil Corporation		W. D. Grimes (NCT-A)
3. Address of Operator		9. Well No.
Box 670, Hobbs, New M	exico 88240	20
4. Location of Well		10. Field and Pool, or Wildot
K 1	980 FEET FROM THE South 2060 FEET FROM	Hobbs
UNIT LETILA		HIIIIIIIIIIIIIIIIII
West	<u>32 точныр 18-5 вансе 38-Е</u> кмрм.	//////////////////////////////////////
THE LINE, SECTION	DN TOWNSHIP RANCL RANCL	
	15. Elevation (Show whether DF, RT, GR, ctc.)	12. County
	3628' GL	Lea
16. Chack	Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
	TENTION TO: SUBSEQUENT	
NOTICE OF IT		
· · · · · · · · · · · · · · · · · · ·	PLUG AND ABANDON	ALTERING CASING
PERFORM REMEDIAL WORK	COMMENCE URILLING OPHS.	PLUG AND ASANDONMENT
TEMPOHARILY SBANDON	CHANGE PLANS CASING TEST AND CEMENT JOB	
PULL OR ALTER CASING	other Abandoned Hobbs	Blinebry and
	Uner .	
OTHER	completed in Hobbs Gr	ъ sл
17 Describe Prepagal or Completed Or	perations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEC RULE 1103.		

4201' PB.

Pulled producing equipment. Ran CI BP and set at 5693' and capped with 4 sacks of cement to 5658', abandoning Blinebry perforations 5829' to 5932'. Perforated Grayburg zone in 5-1/2" casing with 4, 1/2" JHPF at 4234-36'. Ran treating equipment and treated new perforations with 1000 gallons of 15% NE acid. Flushed with 19 barrels of water. Maximum pressure 2800#, minimum 800#. ISIP 1400#, after 5 minutes vacuum. Swabbed water only, with trace of oil. Pulled treating equipment. Set cement retainer at 4212' and squeezed perforation 4234-36' with 50 sacks of Class C cement at 2,000#. Reversed out 11 sacks. Cleaned out to 4201'. Perforated Hobbs zone in 5-1/2" casing with 4, 1/2" JHPF at 4115-17', 4134-36', 4152-54' & 4189-91'. Ran treating equipment and treated new perforations with 2,000 gallons of 15% NE acid. Flushed with water. Maximum pressure 2500#, minimum 900#, ISIP vacuum. Swabbed and cleaned up. Pulled treating equipment. Ran 2-3/8" tubing and set at 4194'. Ran rods and pump and placed well on production. (Well is on same proration unit as well No. 3).

18. Thereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNED C. R. Kanepwo	The Project P	etroleum Engineer	DATE March. 26, 19)76
Jerry Sex.en		· ·	1178 FO 1078	
APPROVED BY Bist 1, SDT	TITLE		ATE 18 5.9 1976	
CONDITIONS OF APPROVAL, IF ANY:	•			