

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		<b>WELL API NO.</b> 30-025-23151
<b>1. Type of Well:</b> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		<b>5. Indicate Type of Lease</b> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
<b>2. Name of Operator</b> Chevron USA, Inc.		<b>6. State Oil &amp; Gas Lease No.</b> 495180
<b>3. Address of Operator</b> 15 Smith Rd. Midland, Tx 79705		<b>7. Lease Name or Unit Agreement Name:</b> H.D. Mc Kinley
<b>4. Well Location</b> Unit Letter <u>H</u> : <u>2310</u> feet from the <u>north</u> line and <u>430</u> feet from the <u>east</u> line Section <u>30</u> Township <u>18-S</u> Range <u>36-E</u> NMPM County <u>Lea</u>		<b>8. Well No.</b> 8
<b>10. Elevation</b> (Show whether DR, RKB, RT, GR, etc.)		<b>9. Pool name or Wildcat</b> Byers Queen

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set 5 1/2 CIBP @ 3625(Byers,Queen)spot 25sx plug fr/3625-3425 Tag @ 3394
2. Displace hole w/MLF 9.5# Brine w/25 Gel p/BBL.
3. Spot 25sx plug fr/2700-2500(Yates,B-salt)
4. Perf 4 holes @ 2000 unable to sqz spot 25sx plug fr/2050-1900 Tag @ 1880
5. Perf 4 holes @ 1400 sqz w/75sx fr/1400-1300(T-salt)Tag @ 1148
6. Perf 4 holes @ 450 (13 3/8 shoe)circ cmt fr/450-surf w/150sx Tag @ surf
7. Install dry hole marker 1-7-03

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER/SUNSET DATE 1-7-03

Type or print name Jimmy BAGLEY Telephone No. 915 520-8756  
(This space for State use)

APPROVED BY Gary W. Wink DATE 1-22-03

Conditions of approval, if any:

GARY W. WINK  
OC FIELD REPRESENTATIVE II/STAFF MANAGER