

Submit 3 Copies To Appropriate District Office

District I
1625 N. French Dr., Hobbs, NM 88240

District II
811 South First, Artesia, NM 88210

District III
1000 Rio Brazos Rd., Aztec, NM 87410

District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-23151
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator Chevron - Texaco, Corp.		6. State Oil & Gas Lease No. 495180
3. Address of Operator P. O. Box 3109, Midland, Texas 79702		7. Lease Name or Unit Agreement Name: H.D. McKinley
4. Well Location Unit Letter <u>H</u> : 2310 feet from the <u>North</u> line and 430 feet from the <u>East</u> line Section <u>30</u> Township <u>18S</u> Range <u>38E</u> NMPM <u>Lea</u> County		8. Well No. 8
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Byers Queen

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPLETION ☐	CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. RIH Tag TOC on CIBP @ +/- 5615', spot 25 Sx plug 5615'-5415' (Blinebry) WOC Tag
2. Displace hole w/MLF, 9.5# Brine w/25# Gel P/BBL
3. Spot 50 Sx plug 3900'-3425' (Queen, 9 5/8" shoe) WOC Tag
4. Spot 25 Sx plug 2700'-2500' (Yates, T-Salt) WOC Tag
5. Cut 5 1/2" Csg @ 2000', L/D Csg
6. Spot 40 Sx plug 2050'-1950' (Stub) WOC Tag
7. Spot 60 Sx plug 1400'-1200' (T-Salt) WOC Tag
8. Spot 60 Sx plug 450'-300' (13 3/8" shoe) WOC Tag
9. 10 Sx Surf, Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James T. Corbett TITLE FACILITY ENGINEER DATE 10/25/01

Type or print name JAMES T. CORBETT Telephone No. 915 688-4438

(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____

Conditions of approval, if any: