

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-23173
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name	State 1-28
8. Well No.	5
9. Foot name or Wildcat	Hobbs-Blinbry

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Chevron U.S.A. Inc.
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	4. Well Location Unit Letter 0 : 330 Feet From The South Line and 2218 Feet From The East

Section 29	Township 18S	Range 38E	NMPM	Lea	County
------------	--------------	-----------	------	-----	--------

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOB ☐ SQZ BLINBRY, DO CIBP, RECOVER 2 PERM. OTHER PACKERS, ACDZ DRINKARD PAY

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PU, POOH W/ PE & PROD TBG P/U WORKSTRING & CIRC RIH & SET @ 5772, BATCH
MIX 400 SX CMT SQZ PERFS 5918-6030 W/250 SX "C" CMT W/.3% D-60, .2% O-46, .5%
S-1 & 150 SX "C" CMT W/ .8% D-59, .2% D-46, 2% H-117 (BWOW), SQZ PERFS 5918-6030
W/ ADD'L 32 1/2 SX CLASS C CMT W/ 16% D-20, 2% D-44, 12#/SX D-24, .2% D-13 TO
3500 PSI SURF PRESS PULL OUT OF CIRC TO 4474 & REV OUT 50 SX (758') CMT ON TOP
OF CIRC POOH & WOC, TIH TAG CMT @ 4840 DO CMT FR 4840-6051, CIRC CLEAN TEST SQZ
TO 500 PSI/30 MIN OK TIH TO 6249 TAG CIBP CIRC CLEAN DRILL UP 1' OF CIBP, TOH W/
BIT TIH WASHOVER SHOE & WASHOVER CIBP @ 6249, TIH W/ WO SHOE & CUT OVER BAKER
MOD F PKR TOH W/FULL RECOVER, TIH CUT OVER BAKER MOD D PKR & PUSH PKR TO 6940
TOH NO RECOVERY TIH W/ PKR TO 6555 ACDZ DRINKARD PERFS 6648-6930 W/4000 GALS
20% NEFE W/ 19.2 TONS CO2 @ 4.7 BPM PMAX 5390 ISIP-2820 15 MIN-950 18 HR FLWG
TST REC'D 24 BO 200 BW W/ FTP 280-145 PSI ON 30/64" CK, LD RODS, RDMO PU TURN
OVER TO PROD FOREMAN.
WORK STARTED 4-9-90 WORK ENDED 4-23-90

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. E. Akins 4/26/90 TITLE Staff Dir. Engr. DATE 4-25-90

TYPE OR PRINT NAME M. E. Akins TELEPHONE NO 93-4121

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 1 1990