

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved,
Budget Bureau No. 42-R-101

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. CIL WELL ☒ GAS WELL ☐ OTHER <u>Drilg</u>		6. LEASE DESIGNATION AND SERIAL NO. <u>AC-032243 (C)</u>	
2. NAME OF OPERATOR <u>Humble Oil & Refg Co.</u>		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR <u>Box 1600 - Midland Texas 79701</u>		8. IF INDIAN, ALLOTTEE OR TRIBE NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) <u>At surface</u>		9. WELL NO. <u>33</u>	
10. FIELD AND POOL, OR WILDCAT <u>Higgs GSA & Blinbry</u>		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>S29, T18S, R38E</u>	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, WPC, etc.)	12. COUNTY OR PARISH <u>Lea</u>	13. STATE <u>N.M.</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Completion attempts

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

No 1 RU. and perf. 7" CSg from 5915 to 5919' w/ shot/ft and 1 shot each from 5929-30-31-32-33-39-43 44-52 and 5953' Treat Blinbry perfs 5915-5953' w/ 1500 gal - 15% NE acid @ 3200# and 1.3 BPM. Swab Test 100% water. Squeezed off perfs w/ 45 sat cmt. Drld out cmt to bottom. Perf 7" CSg from 5915 to 5933' w/ 1 shot/ft. Treat perfs w/ 500 gal 15% NE acid @ 1400psi and .75 BPM. Test well and rec 100% water + No oil or ggs.

Cont on No 2

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: