Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 87240	Revised March 25, 1999 WELL API NO.
District II 811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION	30-025-23252
District III 2040 South Pacheco	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE X FEE
2040 South Pacheco, Santa Fe, NM 87505	6. State Oil & Gas Lease No. 25696
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:	7. Lease Name or Unti Agreement Name
Oil Well X Gas Well Other 2. Name of Operator	8. Well No. 6
2. Name of Operator Texland Petroleum - Hobbs, L.L.C	6. Well No. 6
3. Address of Operator 777 Main Street, Ste 3200 Fort Worth, Tx. 76102	9. Pool name or Wildcat Hobbs: Upper Blinebry
4. Well Location	Hobbs. Upper Buneory
Unit Letter P : 330 feet from the South line and 660 feet from the East line	
Section 29 Township 18S Range 38E	NMPM County Lea
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 6346	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL	SUBSEQUENT REPORT OF:
TEMPORARILY ABANDON	E DRILLING OPNS. PLUG AND
PULL OR ALTER CASING MULTIPLE CASING TE COMPLETION CEMENT JO	ST AND ABANDONMENT DBS
OTHER: OTHER:Plu	g Back
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting and proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 11/1/02 MI BOF Well Service. TOH. TIH w/Alpha CIBP and 2 3/8" tbg. CIBP set TOH & LD 2 3/8" tbg. RU Schlumbereger WL. Run GR-CCL cased hole correlationat 5885 - 5934. Total 38 holes. TIH w/ Model R pkr x 2 7/8 tbg. PSA: 5835. RU Bl Acidize down 2 7/8 tbg w/3500 gal of 15% HCL x 75 ball searlers. Flush w/40 BFV Had good bail sealer action, no ball out. ISIP 0#. Load 124 bbl. RU to swab IFL 50 11/6/02 SITP 90#. IFL 5400. No recovery on swab run. Calc BHP 310#. Release pk 178 jts. 2 7/8 prod. tbg TAC set at 5645, 6 jts of 2 7/8 tbg 1 jt.of 2 7/8 IPC & Seatin & pump. Run 1 1/2 polish rod, 8' of rod subs, 57 1" grade D rods, 69 7/8" grade D rods, 1 3/4x2 1/2x25' HF RHBC insert pump. Load 407 bbls. Move out service unit. 	attach diagram of proposed completion @ 6120'. Dump 20' of cmt on CIBP. on log 5100-6100. Perf 7" casing 2 SPF J Services. Load csg w/295 bbl of FW. W. Air 4.5 bpm, ATP 800#, Max 2600#. Oo. Swab 12 bbl of water. FFL 5000. Tr. Run pkr past perfs. TOH Load 407 bbls run or pinple w/celler @ 5872. Start TOH.
	A A
	JAN 2003
	Hobbs
I hereby certify that the information above is true and complete to the best of my known	owledge and belief
SIGNATURETITLE Regulatory An	alyst DATE
Type or print name Ann Burdette	
Type or print name Ann Burdette (This space for State use)	Telephone No. (817)336-2751
Type or print name Ann Burdette	