

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-23277</u>
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 28
8. Well No. 132
9. Pool name or Wildcat HOBBS (G/SA)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3658' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	2. Name of Operator SHELL WESTERN E&P INC.	3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	4. Well Location Unit Letter <u>L</u> : <u>1880</u> Feet From The <u>SOUTH</u> Line and <u>750</u> Feet From The <u>WEST</u> Line Section <u>28</u> Township <u>18S</u> Range <u>38E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3658' GR			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: <u>Cmt sqzd, OAP & Acd</u> ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-28-89 to 1-09-90:

POH w/prod equip. CO to 4110'. Set CIBP @ 4080' & CICA @ 3955'. Sqzd SA perfs 4019'-60' w/150 SX Cls "C" cmt + 200 SCF N₂/bbl followed by 150 SX Cls "C" cmt + 2% CaCl₂. Drld up CICA/cmt to 4080'. Pres tstd sqz to 500#, held OK 30 min. Drld on CIBP & pushed to 4258' (PBD). Set CIBP @ 4046'. Pres tstd csq & CIBP to 500#. Spot 2 bbls 15% NEFE HCl @ CIBP @ 4046'. Perf'd SA 4019'-41' (2 JSPPF). Acd perfs 4019'-41' w/500 gals 15% NEFE HCl. KO CIBP @ 4046' & CO to 4257'. Inst prod equip & ret'd to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. H. Smitherman

TITLE REGULATORY SUPV.

DATE 2-14-90

TYPE OR PRINT NAME

J. H. SMITHERMAN

(713) 370-3797

TELEPHONE NO.

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

FEB 20 1990

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: