

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-23277

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

SHELL WESTERN E&P INC.

3. Address of Operator

P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)

7. Lease Name or Unit Agreement Name

N. HOBBS (G/SA) UNIT
SECTION 28

8. Well No.

132

9. Pool name or Wildcat

HOBBS (G/SA)

4. Well Location

Unit Letter L : 1880 Feet From The SOUTH Line and 750 Feet From The WEST Line

Section 28

Township

18S

Range

38E

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3658' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Cmt sqz, OAP & Acdz

☒

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.

2. CO to PBTD (4257').

3. Set CIBP @ 4080' & CICK @ 4000'.

4. Sqz SA perfs 4019'-60' w/150 sx Cls "C" cmt + 2% CaCl₂ + 1.5% Howco Suds + 0.75% HC-2 followed by 50 sx Cls "C" cmt + 2% CaCl₂. Cap CICK w/5' cmt. WOC 24 hrs.

5. DO CICK & cmt to CIBP @ 4080'. Pres tst sqz to 500#. DO CIBP @ 4080' to PBTD (4257').

6. Set CIBP @ 4046'. Pres tst csg & CIBP to 500#. Spot 2 bbls 15% NEFE HCl thru +bg.

7. Perf SA 4019'-41' (2 JSPF)

(CONT'D ON REVERSE SIDE)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. H. Smitherman

TITLE

REGULATORY SUPV.

DATE

12-19-89

TYPE OR PRINT NAME

J. H. SMITHERMAN

(713) 870-3797

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 26 1989

8. Acidz perfs 4019'-41' w/500 gals 15% NEFE HCl.
9. KO CIBP @ 4046' & CO to PBTD (4257').
10. Install prod equip & ret well to prod.

RECEIVED
DEC 26 1989
OCD
HOBBS OFFICE