NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE	- Commission	Effective 1-1-65
U.S.G.S.	1	5a. Indicate Type of Lease
LAND OFFICE		
OPERATOR		
		5. State Oll & Gas Lease No.
CLINIO	DV NOTICES AND DEPOSIT	K-5098
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
I. OIL GAS WELL WELL	OTHER. Dry Hole	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Hanson Oil Company		Allied State
3. Address of Operator		9. Well No.
P. O. Box 1515, Roswell, New Mexico 88201		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER J , 2310 FEET FROM THE South LINE AND 1650 FEET FROM		E-K Queen, East
· · · · · · · · · · · · · · · · · · ·	LINE AND FEET FI	mminimm Mark
THE East LINE, SECT	ION 28 TOWNSHIP 18-S RANGE 34-E NM	PM. (
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4031' KB	Lea
16.	Appropriate De T. I. I.	
NOTICE OF	Appropriate Box To Indicate Nature of Notice, Report or	Other Data
NOTICE OF I	NTENTION TO: SUBSEQUE	ENT REPORT OF:
	f===	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
17.5		
work) SEE RULE 1103.	operations (Clearly state all pertinent details, and give pertinent dates, includ	ing estimated date of starting any proposed
3-2-70 Verbal r	equest was made this date, and approved	J. Land Mark Was . Mr.
Ramey of	the NMOCC, Hobbs, to plug and abandon	Dy Mr. Joe D.
well in	the following manner:	the captioned
#0## III	one rollowing manner.	
Sat a	MA or coment when come a contract	Ch. I. Coma
Set a	40 sx. cement plug across perfs. @ 456	54 <b>-</b> 4607*•
Set a	25 sx. cement plug in-and-out of 5-1/2	c" casing where
	shot off and pulled.	
Set a	25 sx. cement plug at the Top of Salt.	•
Set a	25 sx. cement plug in-and-out of 8-5/8	3" @ 2541 <b>.</b>
Set a	10 sx. cement plug at the surface and	erect a
	regulation dry hole marker.	
Clean up	location prior to NMOCC inspection.	
-		
18. I hereby certify that the information	above is true and complete to the best of my knowledge and belief.	
	11	
SIGNED _ Heavens 7	Lehren TITLE Exec. Vice President	3-2-70
	THE BASON VICE IT ESTUBIL	DATE J-L-/U

4 1970