

District I - (505) 393-6161
P. O. Box 1980
Hobbs, NM 88241-1980
District II - (505) 748-1283
811 S. First
Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Road
Aztec, NM 87410
District IV - (505) 827-7131

New Mexico
Energy Minerals and Natural Resources Department
Oil Conservation Division
2040 South Pacheco Street
Santa Fe, New Mexico 87505
(505) 827-7131

Form C
Originated

Submit C
Plus 2
to appr
District

H-0472

APPLICATION FOR
QUALIFICATION OF PRODUCTION RESTORATION PROJECT
AND CERTIFICATION OF APPROVAL

THREE COPIES OF THIS APPLICATION MUST BE FILED WITH THE APPROPRIATE DISTRICT OFFICE OF THE OIL CONSERVATION DIVISION.

- I. Operator: Saga Petroleum LLC OGRID #: 148967
Address: 415 W. Wall, Ste. 835, Midland, Texas 79701
Contact Party: Mark Caldwell Phone: 915-684-4293
- II. Name of Well: State Land Sec. 32 #9 API #: 30-025-23309
Location of Well:
Unit Letter J, 2310 Feet from the South line and 1980 feet from the East line, Section 32,
Township 18S, Range 38E, NMPM, Lea County
- III. Previous Producing Pool Name: Hobbs Upper Blinebry
- IV. Describe the process used to return the Well to _____

*Notify Paul when
completions are approved*

rated

reen



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
DISTRICT I HOBBS
PO BOX 1980, Hobbs, NM 88241
(505) 393-6161
FAX (505) 393-0720

Jennifer A. Salisbury
CABINET SECRETARY

May 18, 1998

Mark Caldwell
Saga Petroleum LLC
415 W Wall, Suite 835
Midland, TX 79701

RE: OIL CONSERVATION DIVISION INCORRECTLY FILED FORM C-139

Dear Mr. Mark Caldwell

We are returning the C-139 form attached because of missing information. Due to a large number of misfiled forms, we are returning form(s) with error(s). On C-139 application for Saga Petroleum LLC, State Land Section 32 # 9 well was recompleted to the Drinkard Formation. The Drinkard Formation is a different pool. No forms (C-102,C-104 & C-105) were ever filed for this recompletion. If this is correct, this well is illegally producing and is hereby order to shut in the above well pending the submission of the required forms (C-102,C-104,C-105, & C-139). If this well was not recompleted to the Drinkard Formation, the only action needed is to correct Paragraph IV of form C-139 and resubmit the corrected C-139.

Please be further advised that delays in processing forms in the future can be avoided by providing all necessary data, signatures and attachments. If you have any questions about this matter and C-139/C-140 applications, please call (505) 393-6161 for assistance from Paul Kautz.

Yours very truly,

OIL CONSERVATION DIVISION

Chris Williams
District I, Supervisor