

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Enr. Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-23309 ✓

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
A-2747

7. Lease Name or Unit Agreement Name

STATE ~~LAND~~ SECTION 32

8. Well No.
9

9. Pool name or Wildcat
HOBBS UPPER BLINEBRY

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
PENROC OIL CORPORATION

3. Address of Operator
P.O. Box 5970, Hobbs, NM 88241-5970

4. Well Location
Unit Letter J : 2130 Feet From The SOUTH Line and 1980 Feet From The EAST Line

Section 32 Township 18 S Range 38 E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
KDB 3648'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: RETURN WELL TO PRODUCTION ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

17 1/2" hole - 13 3/8", 48" @ 364' w/ 160 sxs. Cement circ. 12 1/4" hole - 9 5/8", 36" @ 3799' w/
1140 sxs. TOC: 430' by TS. 8 3/4" hole - 7" Liner: 3573' - 7000' w/ 490 sxs. CBL
showed good bond all across. Halliburton BP @ 5950'. Blinebry perms:
5813', 41, 56, 69, 78, 84, 98, 5922, 26, 32, & 40' (1 jsp) f)
Approx. 4.11.93 - RU w/o rig. PU 2 7/8" tbg. Tally & tag PSTD 5950'. Circ. hole clean,
set pkr & swab test. & necessary chemical job for FeS. Swab test. If
10-15 BOPD/100 mcf - Install pumping unit & put well on pump.
@ a later date selectively perf. & acid. Drinkard - commingle Bl. & Dkd.
A separate C-103 will be submitted when Dkd. perf. are necessary.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. Y. (Merch) Merchant TITLE President

TYPE OR PRINT NAME M. Y. (Merch) Merchant

DATE 3/25/93
TELEPHONE NO. (505) 397-3596

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 26 1993