

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-025-23775 **23375**

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER Injection

2. Name of Operator
Altura Energy, LTD.

3. Address of Operator
P.O. Box 4294 Houston, Texas 79210-4294

4. Well Location
Unit Letter D : 1200 Feet From The North Line and 470 Feet From The West Line
Section 27 Township 18-5S Range 38-E NMPM Lea, NM County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3641 DF

7. Lease Name or Unit Agreement Name
North Hobbs GB/SA Unit
Section 27

8. Well No.
111

9. Pool name or Wildcat
Hobbs GB/SA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work) SEE RULE 1103.

M.I.R.U. Pulling unit N.U. B.O.P.
P.O.H. & L.D. Duoline production tbg & Guiberson Uni-VI packer
R.I.H. w/ 2 3/8" w/s & 5 1/2" CIBP & set @ 4060' (Top perf @ 4161')/
Circ hole w/M.L.F.
Spot 25 sx class-C cmt on top of CIBP 4060' - 3960'.
Perf 4 holes @ 3002' Set 5 1/2" CIBP @ 2902 Squeeze 30 sxs cmt under ret & 25 sxs on top.
Perf 4 holes @ 1807' Set 5 1/2" CIBP @ 1707 Squeeze 30 sxs cmt under ret & 25 sxs on top.
Perf 4 holes @ 397' Pump 150 sxs cmt down 5 1/2" csg CIRC cmt to surface in & out.
Cut off W/H & install dry hole marker.

** Notify NMOC D 24 hrs prior to rigging up.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Sr. P & A Supervisor DATE 12/24/97
TYPE OR PRINT NAME Roger Massey TELEPHONE NO. (915) 530-0907

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

DEC 29 1997