

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103 1 5 1
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator Hanson Oil Company		8. Farm or Lease Name Viersen
3. Address of Operator P. O. Box 1515, Roswell, New Mexico 88201		9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> , 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM THE <u>East</u> LINE, SECTION <u>30</u> TOWNSHIP <u>18-S</u> RANGE <u>39-E</u> NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3617' KB		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-9-70 Upon verbal approval of Mr. Joe Ramey of the NMOCC, Hobbs, the captioned well was plugged and abandoned in the following manner:

All plugs were set in heavy mud.

1. Set 25 sx. plug @ 7425-7512' (T.D. @ 7512')
2. Set 25 sx. plug @ 5791-5878' (Top of Glorietta @ 5834')
3. Set 25 sx. plug @ 4380-4467' (Top of San Andres @ 4423')
4. Set 25 sx. plug @ 2901-2965' (8-5/8" csg. set @ 2923')
5. Set 25 sx. plug @ 576-640' (8-5/8" csg. shot off @ 598')
6. Set 25 sx. plug @ 351-382' (12-3/4" csg. set @ 360')
7. Set 10 sx. plug @ 0-8' and erected a regulation dry hole marker.

The pits were then filled and the location cleaned up prior to inspection by the N.M.O.C.C.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Harry F. Schenck</u>	TITLE <u>Exec. Vice President</u>	DATE <u>3-13-70</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>MAY 20 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		