

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-3496	
7. Unit Agreement Name	
8. Farm or Lease Name	
State AJ	
9. Well No.	
3	
10. Field and Pool, or Wildcat	
Ark. Jct.-San Andres	
15. Elevation (Show whether DF, RT, GR, etc.)	
3807 RT	
12. County	
Lea	

SUNDY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator	
AZTEC OIL & GAS COMPANY	
3. Address of Operator	
P. O. Box 837, Hobbs, New Mexico 88240	
4. Location of Well	
UNIT LETTER K, 2030 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 1 TOWNSHIP 18-S RANGE 36-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
3807 RT	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was plugged and abandoned as follows:

1. Ran C.I.B.P. and set at 5015'. Capped w/4 sx. cement on top.
2. Ran 2-3/8" tubing to 4985' and circulated hole with Mud Laden Fluid.
3. Spotted 25 sx. cement plug at 4080-3865' (est.).
4. Cut 5 1/2" casing at 3115' and pulled out hole.
5. Ran tubing to 3141' and spotted 25 sx. cement plug from 3141-3041'.
6. Spotted 25 sx. cement plug from 2057-1957'.
7. Spotted 25 sxs. cement plug 50' below casing shoe at 379'.
8. Spotted 10 sx. cement plug in top of Surface.
9. Installed Dry Hole Marker and leveled location

Work completed 3-14-73

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

original signed by

LESTER L. DUKE

SIGNED \_\_\_\_\_ TITLE District Superintendent DATE June 11, 1973

APPROVED BY John W. Remyan TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: