

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Encl. Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-23552
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2131
7. Lease Name or Unit Agreement Name: EAST VACUUM GB/SA UNIT TRACT 0449
8. Well No. 115
9. Pool name or Wildcat VACUUM GRAYBURG/SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762	4. Well Location Unit Letter C : 330 feet from the NORTH line and 1650 feet from the WEST line Section 4 Township 18-S Range 35-E NMPM County LEA
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3942' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8-30-01 - MIRU BASIC ENERGY SERVICES.

NOTIFIED GARY WINK WITH NMOC D OF INTENT TO COMMENCE P&A OPERATIONS.

ND WH. NU CLASS 1 BOPE. RU FLOOR & TOOLS. PU & GIH W/ 142 JTS 2.375" N-80 RENTAL WS. TAG CIBP @ 4450'. NOTE: TAGGED AT 1076' WHEN GIH. WORK THRU BAD SPOT. CONTINUE TIH. RU PUMP TRUCK. MIX AND PUMP 40 BBLs 10 PPG MUD LADEN FLUID.

SPOT PLUG #1 - 55 SXS FROM 4450' - 3618'. DISPLACE WITH 14 BBLs MLF. NOTE: PER NMOC D (JOHNNY ROBINSON) OK TO PUMP 55 SXS CMT PLUG. ALL CMT PLUGS ARE CLASS "C" 14.8 PPG/1.32 CFS/6.3 GPS.

POOH LD 48 JTS. BOT @ 2952'.

SPOT PLUG #2 - 25 SXS FROM 2952' - 2574'. DISPLACE WITH 9.5 BBLs MLF. POOH LD 39 JTS. STD BACK 10 STDS. BOT @ 1105'.

NOTE: NMOC D (GARY WINK) OK'D NOT TO RUN A PKR IN THE HOLE DUE TO CONDITION OF CASING.

CONTINUED ON BACK

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE SUPERVISOR, REG./PROR. DATE 9-04-01

Type or print name L. M. SANDERS

Telephone No. (915) 368-1488

(This space for State use)

APPROVED BY Johnny Robinson TITLE DATE JAN 09 2002

Conditions of approval, if any:

GWW

8-31-01 – RU WIRELINE. RIH & PERF 4-1/2" CSG @ 1650' 4 SPF. POOH RD WL. TIH TO 1720'.
SPOT PLUG #3 – MIX AND PUMP 220 SXS CMT 1720'-800'. TAGGED @ 858'.
POOH & DISPLACE TOC INSIDE 4-1/2" DOWN TO 800' WOC. RU WL. RIH & TAG TOC @ 858'.
NMOCD (JOHNNY ROBINSON) OK'D TOC. PERFORATE
4-1/2" CASING AT 411'. PUMP DOWN 4-1/2" CSG & EST CIRC TO SURFACE OUT 8-5/8" X 5-1/2".
8-5/8" HAS HOLE AT SURFACE. SI FOR VACUUM TRUCK.
9-01-01 - BREAK CIRC DOWN 4-1/2" X 8-5/8" FROM 411' TO SURFACE. ND BOPE. NU WH.
PUMP PLUG #4 - 115 SXS FROM 411'-0'. CIRC CMT TO SURFACE.
RDMO BASIC P&A RIG & EQUIP.
PERFORM RECLAMATION WORK. INSTALL DRY HOLE MARKER.

WELL P&A'D