

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
L-1539

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name	
2. Name of Operator AZTEC OIL & GAS COMPANY	8. Farm or Lease Name State "P"	
3. Address of Operator P. O. Box 837, Hobbs, New Mexico 88240	9. Well No. 1	
4. Location of Well UNIT LETTER H , 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 3 TOWNSHIP 18S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) 3719DF	12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 7-7/8" hole to T.D. 5300'. No shows of oil or gas encountered.

Well was plugged in the following manner;

Set 35 sx cement plug at 5300'.
Set 25 sx cement plug at 4000'.
Set 35 sx cement plug at 3150'.
Set 35 sx cement plug at 1700'.
Set 10 sx cement plug at Surface. Hole loaded with mud between plugs.
Appropriate Dry Hole Marker erected at Surface.

Plugged and abandoned 3-19-71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>David Donaldson</u>	TITLE <u>DISTRICT GEOLOGIST</u>	DATE <u>March 24, 1971</u>
APPROVED BY <u>Nathan E. Clegg</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JAN - 3 1972</u>

CONDITIONS OF APPROVAL, IF ANY:

W.S.

RECEIVED

MAR 24 1971

OIL CONSERVATION COMM.
HOBBS N. M.