

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>30-025-23900</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>E-1479</b>
7. Lease Name or Unit Agreement Name <b>State "26" (previously South Vacuum Unit; South Vacuum Unit "26" #2)</b>
8. Well No. <b>2</b>
9. Pool name or Wildcat <b>Wildcat</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3,877' GR</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <b>Dry</b>
2. Name of Operator <b>Baytech, Inc.</b>
3. Address of Operator <b>P.O. Box 10158, Midland, TX 79702</b>

4. Well Location Unit Letter <b>L</b> : <b>1,980</b> Feet From The <b>South</b> Line and <b>710</b> Feet From The <b>West</b> Line Section <b>26</b> Township <b>18-S</b> Range <b>35-E</b> NMPM <b>Lea</b> County
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**PLUGGED & ABANDONED (1-14-92)**

1. CIBP w/35' cmt @ 11400'
2. CIBP w/35' cmt @ 7020' (top of Bone Spring)
3. CIBP w/35' cmt @ 5850' (top of Delaware)
4. 100' stub plug (50' in & 50' out) where 5-1/2" csg cut (tag plug) @ 4500'
5. 100' cmt plug across 8-5/8" shoe (50' in & 50' out) (tag plug) @ 1770'
6. Perf @ top Anhydrite (1777') & set cmt plug in & out 8-5/8" csg
7. 50' below surf shoe; perf & set plug across surf shoe
8. 10 sx surf plug

NOTE: 10# brine mud w/25# gel/bbl

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ben A. Strickling, III TITLE Operations Manager DATE 1/17/92  
TYPE OR PRINT NAME Ben A. Strickling, III TELEPHONE NO. 915/686-9801

(This space for State Use)

APPROVED BY Charlie T. Perrin TITLE OIL & GAS INSPECTOR DATE MAY 06 '92

CONDITIONS OF APPROVAL, IF ANY: