

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-23900
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-1479

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry
2. Name of Operator Baytech, Inc.
3. Address of Operator P.O. Box 10158, Midland, TX 79702

4. Well Location Unit Letter L : 1,980 Feet From The South Line and 710 Feet From The West Line Section 26 Township 18-S Range 35-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,877' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLUG & ABANDON AS FOLLOWS:

- 100' cmt plug (tag plug) or CIBP w/35' cmt @ 11,500'
- 100' cmt plug or CIBP w/35' cmt @ 7,020' (top of Bone Spring)
- 100' cmt plug or CIBP w/35' cmt @ 5,895' (top of Delaware)
- 100' stub plug (50' in & 50' out) where 5-1/2" csg cut (tag plug)
- 100' cmt plug across 8-5/8" shoe (50' in & 50' out) (tag plug)
- perf @ top Anhydrite (1,777') & set cmt plug in & out 8-5/8" csg
- 50' below surf shoe; perf & set plug across surf shoe
- 10 sx surf plug

NOTE: 10# brine mud w/25# gel/bbl

PROPOSED DATE TO BEGIN: 2/22/91

I hereby certify that the information above is true and correct to the best of my knowledge and belief.

SIGNATURE Ben A. Strickling, III TITLE Operations Manager DATE 2/18/91
TYPE OR PRINT NAME Ben A. Strickling, III TELEPHONE NO. 915/686-9801

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24
HOURS BEFORE THE BEGINNING OF
ANY OPERATIONS FOR THE C-103