Internation of the second s	NO. OF COPIES REC		7		
SANTA FE Interview Site is in the interview of the interview o			-	Form C-103 Supersedes Old	
File Indicate Type of Lease USG 0.1 State (1): Set (2): Set (
U.S. d. AND OFFICE Image: Support NOTICES AND REPORTS ON WELLS				Elective 1-1-00	
AND OFFICE Departure			-	5a. Indicate Type of Lease	
OPERATOR D. Buttor D. C. Schellander Son. SUNDRY NOTICES AND REPORTS ON WELLS. Sone of D. Schellander Sone. 1 St. () With C. Schellander Sone Schellander Schellander Sone Schellander Schellander Sone Schellander Sone Schellander Sone Schellander Sone Schellander Sone Schellander Schellander Schellander Schellander Schellander Schellander Schellander Sone Schellander Schelander Schelander Schelander Schellander Schelander Schellander Sc			-	State XX Fee	
SUNDEY NOTICES AND REPORTS ON WELLS 1 One of the product intervent of submit intervent intervent. 1 One of Chemistry 2. Now of Chemistry Attack of Operation 3. Now of Chemistry Now of Chemistry 4. Location of well 10. Find and Heal, or Wells 3. Now of Chemistry 10. Find and Heal, or Wells 4. Location of well 10. Find and Heal, or Wells 1. Location of Well 10. Find and Heal, or Wells 1. Location of Well 10. Find and Heal, or Wells 1. Location of Well 10. Find and Heal, or Wells 1. Location of Well 10. Find and Heal, or Wells 1. Location of Well 10. Find and Heal, or Wells 1. Location of Well 11. Find and Heal, or Wells 1. Location of Well 12. Start (Start Medice) 1. Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Subsequent Xee 1. Set cast if on hridge plug at 10,700' & cao with 30' cement. 2. Cut and pull 4-1/2" casing from SOOC' cr free point. 3. Spot 33 sx plug at 8100'. 4. Spot 33 sx plug at 4750' in and out of 8-5/8" casing. 2. Hole will be loaded with 9.5# fluid and teaporarily abandoned untill <td></td> <td></td> <td>-</td> <td>5. State Oil & Gas Lease No.</td>			-	5. State Oil & Gas Lease No.	
1. State III and IIIIIIIIIIIIIIIIIIIIIIIIIIIIIII				B-5659	
While IX math I overall 2. Nome of Committee F. L. L. trown, Jr. State "B" 3. Address of Constance C. Well No. State "B" 3. Address of Constance C. Well No. C. Well No. 4. Location of Well II. Fraction of Nome. State "B" 0 unit Letters I 2310 rect recovering me East	(DO NOT USE	SUND			
K. L. LTOWN, Jr. State "E" 3. Astrono of Well 3. Astrono of Well 4. Location of Well 1. 2310 wirt Letters 1. 2310 ref East 1. 2000 ref East 1. 2000 ref East 1. 2000 ref East 1. 2000			OTHER-	7. Unit Agreement Name	
 3. Address of Operator 3. Address of Operator 3. Address of Operator 4. Location of Well 5. Elevention (Clearly Mell Device of Notice, Report of Other Data Subsequent Report of: 4. Location of Well 4. Location of Well 5. Elevention (Clearly state all portional details, and give partisent dates, including estimated date of starting any proposed or Completed Operations (Clearly state all portional details, and give partisent dates, including estimated date of starting any proposed or Completed Operations (Clearly state all portional details, and give partisent dates, including estimated date of starting any proposed or Completed Operations (Clearly state all portions details, and give partisent dates, including estimated date of starting any proposed of the propose to temporarily abandon this well and plut hack as follows: 1. Set cast from bridge plug at 10,700¹ % cap with 30¹	· ·	. Lrown,	Jr.		
4. Location of Well 10. Field and Pool, 5: Wildest unit cerves 1 2310 represented for the section of the sectin of the sect of the section of the section of the secti	3. Address of Opera	tor		9. Well No.	
<pre>11. Set cast iron bridge plug at 10,700' & cap with 30' cement. 2. Cut and pull 4-1/2" casing from COOC' or free point. 3. Spot 30 sx plug at 8100'. 4. Spot 30 sx plug at 4750' in and out of P-5/8" casing. 5. Hole will be loaded with 9.5# fluid and temporarily abandoned until 3. Spot 60 sx plug at 4750' in and out of P-5/8" casing. 5. Spot 60 sx plug at 4750' in and out of P-5/8" casing. 5. Spot 60 sx plug at 4750' in and out of P-5/8" casing. 5. Spot 60 sx plug at 4750' in and out of P-5/8" casing. 5. Spot 60 sx plug at 4750' in and out of P-5/8" casing. 5. Spot 60 sx plug at 4750' in and out of P-5/8" casing. 5. Spot 60 sx plug at 4750' in and out of P-5/8" casing. 5. Spot 60 sx plug at 4750' in and out of P-5/8" casing. 5. Hole will be loaded with 9.5# fluid and temporarily abandoned until San Andres recompletion is attempted. THE COMMISSION MUST BE NOTHED 24 HOURS PROVED. 14. thereby certify that the information abage is true and expediet to the best of my knowledge and belief. second B. D. Baker Mark 100 mark 200 mark 2</pre>	303	Midland T	ower Lidland, Texas 79701	1	
The East				10, Field and Pool, or Wildcat	
15. Elevention (Show whether DF, RT, CR, etc.) 15. County 12. County 12. '0L 16. County 17. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Subsequent REPORT OF: 17. Describe Proposed or INTENTION TO: Subsequent REPORT OF: Subsequent	UNIT LETTER	<u> </u>	2310 FEET FROM THE South LINE AND 360 FEET FRO	M NW Vacuum Wolfcamp	
16: Lea 16: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PREFORM REMEDIAL WORK PLUG AND ABANGON If workship Alangon PLUG AND ABANGON OTHER Commence Officient Report of Other Data OTHER Commence Officient Report of PLUG AND ABANGON Stand Proceed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated dute of starting any proposed OTHER To be cast iron bridge plug at 10,700' % cap with 30' cement. 2. Cut and pull 4-1/2" casing from \$2000' cr free point. 3. Spot 30 sx plug at 8100'. 4. Spot 30 sx plug at 4750' in and out of \$2-5/8" casing. <td>THE East</td> <td>LINE, SECT</td> <td>TIONTOWNSHIPRANGE</td> <td></td>	THE East	LINE, SECT	TIONTOWNSHIPRANGE		
 Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: PLUG AND ADANDON PLUG ADANG ADANDON PLUG ADANG AD					
Check Appropriate Box 10 indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUG AND ADAMDON PULL OR ALTER CASING PULL OR ALTER C	$\overline{\mathbf{V}}$				
 TEAPORABLY ARANDON TEAPORABLY ARANDON PULL OR ALTER CASING COMMENCE DEFLLING OPNS. CASING TEST AND CEMENT JOB OTHER COMMENCE DEFLLING OPNS. CASING TEST AND CEMENT JOB OTHER I. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed work/ see Rule 1103. We propose to temporarily abandon this well and plug back as follows: Set cast iron bridge plug at 10,700' & cap with 30' cement. Cut and pull 4-1/2" casing from \$200C' or free point. Spot 30 sx plug at 8100'. Spot 30 sx plug at 6050'. Spot 60 sx plug at 4750' in and out of 8-5/8" casing. Hole will be loaded with 9.5# fluid and temporarily abandoned until San Andres recompletion is attempted. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. 18. I hereby cently that the information above is true and complete to the best of my knowledge and belief. THE Petroleum Engineer case and belief. 	10.				
 17. Describe Proposed or Completed Operations (Clearly state all perinent datas, and give pertinent dates, including estimated date of starting any proposed work) see Rule 1103. We propose to temporarily abandon this well and plug back as follows: Set cast iron bridge plug at 10,700' & cap with 30' cement. Cut and pull 4-1/2" casing from \$2000' or free point. Spot 30 sx plug at 8100'. Spot 30 sx plug at 6050'. Spot 60 sx plug at 4750' in and out of 8-5/8" casing. Hole will be loaded with 9.5# fluid and temporarily abandoned until San Andres recompletion is attempted. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PlugGink OPERATIONS FOR THE C-103 TO BE APPROVED. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 	TEMPORARILY ABAND Pull or alter casi	on K	COMMENCE DRILLING OPNS.		
 work) SEE RULE 1103. We propose to temporarily abandon this well and plug back as follows: Set cast iron bridge plug at 10,700' & cap with 30' cement. Cut and pull 4-1/2" casing from \$2000' or free point. Spot 30 sx plug at 8100'. Spot 30 sx plug at 6050'. Spot 60 sx plug at 4750' in and out of 8-5/8" casing. Hole will be loaded with 9.5# fluid and temporarily abandoned until San Andres recompletion is attempted. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 	OTHER				
 Set cast iron bridge plug at 10,700' & cap with 30' cement. Cut and pull 4-1/2" casing from \$2000' or free point. Spot 30 sx plug at 8100'. Spot 30 sx plug at 6050'. Spot 60 sx plug at 4750' in and out of 8-5/8" casing. Hole will be loaded with 9.5# fluid and temporarily abandoned until San Andres recompletion is attempted. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BECINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and bellef. 			Operations (Clearly state all pertinent details, and give pertinent dates, includin	ig estimated date of starting any proposed	
 Cut and pull 4-1/2" casing from SODC' or free point. Spot 30 sx plug at 8100'. Spot 30 sx plug at 6050'. Spot 60 sx plug at 4750' in and out of 8-5/8" casing. Hole will be loaded with 9.5# fluid and temporarily abandoned until San Andres recompletion is attempted. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 	We p	ropose to	temporarily abandon this well and plug	back as follows:	
 3. Spot 30 sx plug at 8100'. 4. Spot 30 sx plug at 6050'. 5. Spot 60 sx plug at 4750' in and out of 8-5/8" casing. 6. Hole will be loaded with 9.5# fluid and temporarily abandoned until San Andres recompletion is attempted. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED B. D. Baker Model THE Petroleum Engineer PATE 10-11-73 	1.	Set cast	iron bridge plug at 10,700' & cap with 3	30' cemant.	
 4. Spot 30 sx plug at 6050'. 5. Spot 60 sx plug at 4750' in and out of 8-5/8" casing. 6. Hole will be loaded with 9.5# fluid and temporarily abandoned until San Andres recompletion is attempted. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED B. D. Baker Model THE Petroleum Engineer DATE 10-11-73 	2.	Cut and p	ull 4-1/2" casing from \$2000' or free pot	int.	
 5. Spot 60 sx plug at 4750' in and out of 8-5/8" casing. 6. Hole will be loaded with 9.5# fluid and temporarily abandoned until San Andres recompletion is attempted. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED B. D. Baker Model THE Petroleum Engineer DATE 10-11-73 	3.	3. Spot 30 sx plug at 8100'.			
 E. Hole will be loaded with 9.5# fluid and temporarily abandoned until San Andres recompletion is attempted. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED B. D. Baker Model TITLE Petroleum Engineer DATE 10-11-73 	4.	4. Spot 30 sx plug at 6050'.			
San Andres recompletion is attempted. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED B. D. Baker Abada TITLE Petroleum Engineer DATE 10-11-73	5.	Spot 60 sx plug at 4750' in and out of 8-5/8" casing.			
SIGNED B. D. Baker Mabal TITLE Petroleum Ergineer DATE 10-11-73	έ.	Hole will San Andre	res recompletion is attempted. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103		
			bab le		
Orig	SIGNED B. D	<u>. Baker</u>	1 10 10 Tay TITLE Petroleum Ergineer	DATE73	
			Orig		
	APPROVED BY		TITLE	DATE	