## .D STATES DEPARTMENT OF THE INTERIOR Other instructions on verse side) GEOLOGICAL SURVEY

SUBMIT IN TRIPL ZE\*

FRACTURE TREATMENT

SHOOTING OR ACIDIZING .

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

NM 04591

OLD IDDIX	LICTICES	A 1 15	DEDODEC	ON 1 14/51	
SUNDRY	NORRES	AND	REPORTS	UN WELL	

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

ALTERING CASING

ABANDONMENT\*

(Do not use this form for propose Use "APPLICA"	ils to drill or to deepen or plug back to a FION FOR PERMIT—" for such proposals,)	different reservoir.			
OIL GAS GAS WELL OTHER			7. UNIT AGREEMENT NA	ME	
2. NAME OF OPERATOR	8. FARM OR LEASE NAME				
Mobil Oil Corporation	E. K. Queen Unit Tr. 6				
3. ADDRESS OF OPERATOR	9. WELL NO.				
Three Greenway Plaza Ea	17	•			
4. LOCATION OF WELL (Report location cl	10. FIELD AND POOL, OR WILDCAT				
See also space 17 below.) At surface	E.K. Yates 7/Rivers Queen				
Unit E, 1450' FNL, & 70	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA				
			Sec. 19, T-18	3-S, R-34-E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH	13. STATE	
	3965 GR		Lea	N. M.	
16. Check Ap	propriate Box To Indicate Nature o	of Notice, Report, or C	)ther Data		
NOTICE OF INTEN	TION TO:	SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	ULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING V	WELL	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1/28/77 4650 TD, 4605 PBTD, perfs 4368-4412. MIRU Eunice DD unit 1/27/77, POH rods.

1/29/77 4650 TD, 4605 PBTD, perfs 4368-4412. POH tbg Howco set cmt ret @ 4215, Knox sq perfs 4368-4410 w/100 sxs H spot 5 sxs on cmt ret @ 4215, load csg w/9.2# br, spot 25 sx plug 3030-3245, 25 sx 1538-1753, SDFN.

1/31/77 Remove BOP's, spot 10 sxs in surf, weld on plate install P&A marker, rel Eunice WS 10:00 AM, 1/29/77, well P&A.

FINAL REPORT.

FRACTURE TREAT

SHOOT OR ACIDIZE REPAIR WELL

18. I hereby certify that the foregoing is true and correct			
SIGNED Siggy Schweikhardt	Authorized	d Agent	2-8-77
(This space for Federal or State office use)		OBBROAFA	
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	JUL 1 3 1979 ATT	
*S2e	Instructions on Reverse	SOLING DISTRICT ENGINEER	3