NU. OF COFIES RECEIVED	_	Form C-103
DISTRIBUTION	·	C-102 and C-103
SANTA FE	W MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.\$.G.\$.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		B-2516
(DO NOT USE THIS FORM FOR P	RY NOTICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVO ATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	18.
1.		7. Unit Agreement Name
OIL GAS WELL WELL	OTHER. Dry Hole	SMGSAU
2. Name of Operator	8. Farm or Lease Name	
Cities Service	Tract 7	
3. Address of Operator		9. Well No.
Box 4906 – M	7	
4. Location of Well		10. Field and Pool, or Wildcat
0	100 FEET FROM THE South LINE AND 1430	Maljamar (G-SA)
UNIT LETTER	FEET FROM THELINE AND	FEET FROM
East	100 _ 29 TOWNSHIP _ 175 33E	
THELINE, SECT	TION TOWNSHIP RANGE	—м <i>рм.</i> ())))))))))))))))))))))))))))))))))))
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4064' DF		Lea
16.		
	Appropriate Box To Indicate Nature of Notice, Rep	
NOTICE OF	INTENTION TO: SUB	SEQUENT REPORT OF:
[]		<u> </u>
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JO	τ∎
	OTHER	
OTHER		
12 Describ Described 2 and 1		
 Describe Proposed or Completed (work) SEE RULE 1103. 	Operations (Clearly state all pertinent details, and give pertinent dates	s, including estimated date of starting any proposed
The above well was plug	gged and abandoned in the following manner	:

1. MIRU pulling unit and loaded hole with mud laden fluid.

- 2. Set a CIBP in 5-1/2" csg @ 4207 & dumped a 5 sx cement plug on top of CIBP @ 4207' 4167'.
- 3. Shot and pulled 54 jts (1738') of 5-1/2'' csg.
- 4. Spotted a 25 sx cement plug 1/2 in and 1/2 out of 5-1/2 csg @ 1788' 1688'.
- 5. Spotted a 40 sx cement plug across the top of salt @ 1380' 1280'.
- 6. Spotted a 30 sx cement plug 1/2 in and 1/2 out of 8-5/8" csg shoe @ 840' 740'.
- 7. Spotted a 10 sx cement surface plug @ 30' 0' with a 4" dry marker extending 4' above the surface to designate a dry hole.
- 8. Location will be cleared of all equipment and debris and your office will be notified for final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED_Strutcher	Region Operation Manager	DATE July 10, 1973
APPROVED BY JAMEN W. Runyan CONDITIONS OF APPROVAL, IF ANY:		DATE