

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO. 30-025-24329
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		7. Lease Name or Unit Agreement Name: Vacuum Grayburg San Andes Unit
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	8. Well No. #49	
2. Name of Operator Texaco Exploration & Production, Inc.	9. Pool name or Wildcat Vacuum Grayburg	
3. Address of Operator P. O. Box 3109, Midland, TX 79702		
4. Well Location Unit Letter <u>F</u> : <u>1390</u> feet from the <u>North</u> line and <u>2580</u> feet from the <u>West</u> line Section <u>1</u> Township <u>18S</u> Range <u>34E</u> NMPM Lea County		
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- Unable to set CIBP bad Csg @ 4013' Sqz w/175 Sx Tag Cmt @ 3835'
- Displace hole w/MLF 9.5# brine w/25# gel P/BBL
- Perf 4 1/2" csg @ 2400' unable to sqz spot 30 Sx plug 2465'-2200' (B-Salt)
- Perf well @ 1300' Sqz w/60 Sx 1300'-1100' (T-Salt) Tag @ 1010'
- Perf well @ 425' Circ cmt between 8 5/8" shoe 4 1/2" csg to Surf w/130 Sx
- Install dry hole marker. 06/01/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER DATE 6/01/01

Type or print name Jimmy BAGLEY Telephone No. 915 683-4996

(This space for State use)

APPROVED BY [Signature] TITLE Ed Lep DATE 10-18-01  
Conditions of approval, if any:

GWV