

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-025-24329
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No. 13-1080-1
Lease Name or Unit Agreement Name Vacuum Grayburg San Andres Unit
Well No. 49
Pool name or Wildcat Vacuum Grayburg San Andres
Unit Letter <u>F</u> : <u>1390</u> Feet From The <u>North</u> Line and <u>2580</u> Feet From The <u>West</u> Line
Section <u>1</u> Township <u>18-S</u> Range <u>34-E</u> NMPM <u>Lea</u> County
Elevation (Show whether DF, RKB, RT, GR, etc.)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Injection Well
Name of Operator Texaco E & P
Address of Operator P.O.Box 3109 Midland, Texas 79702
Well Location Unit Letter <u>F</u> : <u>1390</u> Feet From The <u>North</u> Line and <u>2580</u> Feet From The <u>West</u> Line
Section <u>1</u> Township <u>18-S</u> Range <u>34-E</u> NMPM <u>Lea</u> County
Elevation (Show whether DF, RKB, RT, GR, etc.)

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ANBANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Notify OCD of intent to plug
- 2) MIRU, NU/BOP
- 3) POOH w/tbg and packer
- 4) Set CIBP @ 4150', spot 20 sx cement to 3950', WOC/test
- 5) Mix and circ 10# mud from 3950' to surface
- 6) Perf @ 2760' and sqz 30 sx cement 2660-2760' WOC/tag
- 7) Perf @ 1830' and sqz 30 sx cement 1730-1830' WOC/tag
- 8) Perf @ 1660' and sqz 40 sx cement, WOC/tag (shoe plug) tag no lower than 1608'
- 9) Set 10 sx surface plug 0-30'
- 10) RDMO-cut off well head, install dry hole marker, clean location

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE CLOSURE TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David W. Deax TITLE Reservoir Engineer DATE 10-12-98

TYPE OR PRINT NAME Dave Deax TELEPHONE NO. (915) 688-4492

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE OCT 12 1998

CONDITIONS OF APPROVAL, IF ANY:

Orig. Signed by  
Paul Kautz  
Geologist